central Goldfields Shire (Former city of Maryborough) Maryborough Heritage Study 1992 Book 3 - Higham - McKean Dook 3 Higham to Mckean

By the section is

# Hi gham

McKean

# **HERITAGE STUDY**

BOOK 2

HIGHAM STREET MARYBOROUGH

<u>TO</u>

MCKEAN STREET MARYBOROUGH

# **STREET INDEX**

# BOOK 3

# **HIGHAM STREET MARYBOROUGH**

# <u>TO</u>

# MCKEAN STREET MARYBOROUGH

- 1) Higham Street
- 2) Hilton Street
- 3) Holyrood Street
- 4) Inkerman Street
- 5) Kars Street
- 6) Kennedy Street
- 7) Logan Street
- 8) Lowenstein Street
- 9) Luke Court
- 10) McKean Street

3 HIGHAM STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s 1912? ■ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE    Exploration and Pastoral Settlement   Local Industries   Town Plan   Local Government   and Growth of the Town   Public and   Public and   Private Building   Victorian   Inter-war Housing   Post World War Two
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  □ Heritage Item Alone  RECOMMENDATION  Should be conserved - C  Conservation Area
FOR SALE  SOLI SI-12300  FOR SALE  SOLI SI-12300
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Garden Designer  Garden Planting  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Historic Significance  Horticultural Significance  Horticultural Significance  Manufacturing Significance  Streetscape Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual Design, Features  Typical Design, Features
DESCRIPTION  Place Contains  Main Building □ Garden of Significance or Interest □ More than One Main  Outbuilding/s of □ Individual Planting of Significance or Significance □ Interest as □ Buildings of No  Garden or Other □ Part of Garden OR □ Individually Structures □ Front Fence OR □ Visible  Other □ Other Fences of Significance or Interest

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
Brick - Face
Tiles  Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  Intact □ Additions □ Alterations □ Secondary Elements □ Part of the Significance □ Part of the Significance □ Detract from the Significance □ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use ☐ Disused ☐ Maintenance Unsympathetic Use ☐ Sympathetic Use ☐ Cosmetic Maintenance Required ☐ Threatened by Redevelopment ☐ Required ☐ Threatened by Subdivision

5 HIGHAM STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s 1902? □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries Town Plan □ Transport (Mining and Other)□ Socio-economic □ Public and □ Private Building □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing □ Post World War Two
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  Entire Place (Heritage and Site)  Heritage Item Alone  Conservation Area  Including Other Sites  Other
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Designer  Garden Planting  Garden Planting  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Historic Significance  Horticultural Significance  Horticultural Significance  Manufacturing Significance  Manufacturing Significance  Streetscape Significance  Townscape Significance  Townscape Significance  Townscape Significance  Townscape Significance
DESCRIPTION  Place Contains   Main Building  Outbuilding/s of Significance  Individual Planting of Significance or Building of Significance  Interest as  Garden or Other Structures  □ Other  Other Fences of Significance or Interest  □ Wore than One Main Building of Significance Buildings of No Significance Significance □ Visible □ Other Fences of Significance or Interest

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique □ Flat Fronted ■ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS
■ All of the One Basic Material  □ More Than Two Basic Materials  □ Original (1) and Later () Section Materials  Walls
□ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
Pitched Gabled □ Lean-to □ Timber Shingles □ Flat □ No Eaves □ Narrow Eaves □ Canvas □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet □ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck □ Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium Exterior Doors
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use

□ Other

WEATHERBOARD HOUSE,
7 HIGHAM STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s 1895? □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE    Exploration and Pastoral Settlement   Cold Discoveries   First Survey and Original Pastoral Settlement   Local Industries   Town Plan   And Growth of the Town   Public and   Public and   Public and   Private Building   Post World War Two
DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE  EXTENT OF SIGNIFICANCE ■ Entire Place (Heritage and Site) □ Including Other Sites
RECOMMENDATION Should be conserved - C Conservation Area
CULTURAL SIGNIFICANCE
Basis of Significance  Architectural Significance
□ Architect □ Designer □ Builder □ Manufacturer of Components □ Tradesman □ Garden Design □ Garden Planting □ Garden Maintenance and Development □ Associations with Person/Group/Body □ Botanical Significance □ Construction Significance □ Engineering Significance □ Historic Significance □ Horticultural Significance □ Landscape Significance □ Manufacturing Significance □ Streetscape Significance □ Townscape Significance □ In Comparison With Other Places in Maryborough □ Typical □ Unusual □ Unusual Design, Features □ Good Quality Design, Features □ Typical Design, Features
DESCRIPTION
Place Contains  Main Building □ Garden of Significance or Interest □ More than One Main □ Outbuilding/s of □ Individual Planting of Significance or Significance □ Interest as □ Building of Significance □ Buildings of No □ Garden or Other □ Part of Garden OR □ Individually Significance □ Visible

 $\square$  Other Fences of Significance or Interest

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials
□ More Than Two Basic Materials       □ Original (1) and Later () Section Materials         Walls       □ Brick - Face       □ Brick - Rendered       □ Brick - Painted Later?       □ Corrugated Iron         □ Brick - Probably Painted       □ Stone       □ Timber Stud Framed/         □ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed
Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction  Roof (Main Roof (1), Additions (2)-)  □ Pitched □ Gabled □ Lean-to □ Timber Shingles □ Flat □ No Eaves □ Narrow Eaves □ Canvas □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet □ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck  Tiles
Windows   □ Original Some Later All Later Leadlight, Stained Glass   Timber Steel Framed Aluminium   Exterior Doors   □ Original Some Later All Later Leadlight, Stained Glass   □ Timber Timber and Glass Metal
SIGNIFICANT FEATURES
INTACTNESS  Intact  Additions  Secondary Elements  Part of the Significance  □ Detract from the Significance  □ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use

8 HIGHAM STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s □
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries □ Town Plan □ Local Government and Growth of the Town □ Transport □ (Mining and Other)□ Socio-economic □ Public and □ Private Building □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing
DEGREE OF SIGNIFICANCE EXTENT OF SIGNIFICANCE    Entire Place (Heritage and Site)   Including Other Sites   Other    Heritage Item Alone   Other    RECOMMENDATION   Should be conserved - C   Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Garden Designer  Garden Planting  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Historic Significance  Horticultural Significance  Horticultural Significance  Manufacturing Significance  Streetscape Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual  Unusual Design, Features
DESCRIPTION  Place Contains   Main Building  □ Outbuilding/s of Significance or Interest □ More than One Main  □ Outbuilding/s of Significance or Interest as □ Building of Significance  □ Garden or Other □ Part of Garden OR □ Individually Significance  Structures □ Front Fence OR □ Visible  □ Other Fences of Significance or Interest

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  ■ Rectangular □ Other
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Cellar □ Basement Cellar  WALLS
■ All of the One Basic Material □ Two Basic Materials □ More Than Two Basic Materials □ Original (1) and Later () Section Materials Walls
□ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
☐ Flat ☐ No Eaves ☐ Narrow Eaves ☐ Canvas ☐ Wide Eaves ☐ Slate Cladding ☐ Terracotta Tile ☐ Flat Metal Sheet ☐ Corrugated Iron ☐ Patent Metal Roofing ☐ Timber Shingles ☐ Metal Deck ☐ Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required □ Required

WEATHERBOARD FORMER SCHOOLHOUSE, 8 HIGHAM STREET, MARYBOROUGH.

CONSTRUCTED:

1900S/1910S

MOVED HERE:

MID 20TH CENTURY?

THEMES ILLUSTRATED BY THIS PLACE:

**EDUCATION** 

PRIVATE BUILDING - POST

WORLD WAR TWO

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE:


ENTIRE BUILDING AND SITE TO A RADIUS OF 10 METRES


TO A MADIOS OF TO METRES


**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION

CONSERVATION AREA: MARYBOROUGH EAST











- 2 -

Weatherboard Former Schoolhouse Cont.

### CULTURAL SIGNIFICANCE:

A standard Edwardian era timber government school building, this structure is the only one in the City of Maryborough and evidently was moved here some time this century. This type of school, one or two classrooms in size, was commonly used throughout Victoria for small settlement schools and this would be where this building was brought from.

### HISTORY:

Original Use:

State School on a different site.

Present Use:

Storage shed.

Original Owner:

Education Department of

Victoria

Architects:

Public Works Department of

Victoria

There are a (large) number of identical school buildings throughout Victoria.

### DESCRIPTION:

Style Edwardian.

Design standard.

Plan rectangular main body with projecting rectangular front porch and cloakroom.

Single storeyed.

Walls timber stud construction, weatherboard clad.

Roof gabled with eaves, corrugated iron clad.

Features are the front porch and cloakroom, gables and the windows.

### CONSERVATION GUIDELINES:

Re-stump.
Catch up on neglected maintenance.
Repaint in original/period paint colours.
Ensure roof and ground-water is taken well away from the building.
Return altered parts of exterior to original design.

### CITY OF MARYBOROUGH HERITAGE STUDY WEATHERBOARD HOUSE, 9 HIGHAM STREET, MARYBOROUGH. BUILT 1850s □ 1860s □ 1870s 1880s or 1890s ■ 1900s or 1910s □ 1920s-1930s □ 1940s ☐ 1950s □ 1960s □ 1970s □ 1980s □ 1990s THEMES IDENTIFIED BY THIS PLACE Exploration and ☐ Gold Discoveries ☐ First Survey and Original ☐ Local Government Pastoral Settlement Local Industries Town Plan and Growth of the Town Transport (Mining and Other) ☐ Socio-economic ☐ Public and ☐ Health Education Mix in the Town Private Building □ Notable Men Victorian Religion ☐ Sport and Recreation and Women ☐ Public and Private Planting **Edwardian** ☐ Inter-war Housing ☐ Post World War Two DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE **EXTENT OF SIGNIFICANCE** Entire Place (Heritage and Site) ☐ Including Other Sites ☐ Heritage Item Alone □ Other RECOMMENDATION Should be conserved - C Conservation Area **CULTURAL SIGNIFICANCE Basis of Significance** ☐ Architectural Significance ☐ Architect □ Designer ☐ Builder ☐ Manufacturer of Components ☐ Tradesman ☐Garden Design ☐ Garden Planting ☐ Garden Maintenance and Development ☐ Associations with Person/Group/Body ☐ Botanical Significance ☐ Construction Significance ☐ Engineering Significance ☐ Historic Significance ☐ Horticultural Significance ☐ Landscape Signficance ☐ Manufacturing Significance ■ Streetscape Significance ☐ Townscape Significance In Comparison With Other Places in Maryborough ☐ Typical ☐ Unusual ☐ Unusual Design, Features ☐ Good Quality Design, Features ■ Typical Design, Features DESCRIPTION

DI	200	Contains	
$\mathbf{r}_{1}$	ace	Contains	

e (	Contains			
	Main Building	Garden of Significance or Interest		More than One Main
	Outbuilding/s of	Individual Planting of Significance or		Building of Significance
	Significance	Interest as		Buildings of No
	Garden or Other	☐ Part of Garden OR ☐ Individually		Significance
	Structures	Front Fence OR		☐ Visible
	Other	☐ Other Fences of Significance or Intere	st	

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS
All of the One Basic Material  ☐ Two Basic Materials ☐ Original (1) and Later () Section Materials  Walls
Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use

11 HIGHAM STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries □ Town Plan □ Local Growth of the Town □ Transport □ (Mining and Other)□ Socio-economic □ Public and □ Private Building □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing □ Post World War Two
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  □ Heritage Item Alone  RECOMMENDATION  Should be conserved - C  Conservation Area
Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  ☐ Architectural Significance ☐ Architect ☐ Designer ☐ Builder ☐ Manufacturer of Components ☐ Tradesman ☐ Garden Design ☐ Garden Planting ☐ Garden Maintenance and Development ☐ Associations with Person/Group/Body ☐ Botanical Significance ☐ Construction Significance ☐ Engineering Significance ☐ Historic Significance ☐ Horticultural Significance ☐ Landscape Significance ☐ Manufacturing Significance ☐ Streetscape Significance ☐ Townscape Significance ☐ In Comparison With Other Places in Maryborough ☐ Typical ☐ Unusual ☐ Unusual Design, Features ☐ Good Quality Design, Features ☐ Typical Design, Features
DESCRIPTION  Place Contains  Main Building  Outbuilding/s of Significance  Individual Planting of Significance or Interest Significance  Interest as  Garden or Other Structures  Part of Garden OR ☐ Individually Structures  Other  Other  Other ☐ Other Fences of Significance or Interest  U More than One Main Building of Significance Buildings of No Significance Significance □ Visible

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/ EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full □ Cellar □ Basement Cellar
■ All of the One Basic Material □ Two Basic Materials □ More Than Two Basic Materials □ Original (1) and Later () Section Materials Walls
Brick - Face
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium ☐ Exterior Doors ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  Intact
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Threatened by Subdivision □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

# WEATHERBOARD COTTAGE AND PICKET FENCE,

21 HIGHAM STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and □ Gold Discoveries □ First Survey and Original □ Local Government and Growth of the Town □ Transport □ (Mining and Other) □ Socio-economic □ Public and □ Education □ Health □ Mix in the Town □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing □ Post World War Two
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  □ Heritage Item Alone  □ Other  RECOMMENDATION  Should be conserved - C  □ Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Designer  Garden Design  Garden Planting  Garden Manufacturer of Components  Garden Manufacturer of Components  Garden Manufacturer of Components  Engineering Significance  Historic Significance  Horticultural Significance  Manufacturing Significance  Streetscape Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual Design, Features
DESCRIPTION  Place Contains

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  ■ Rectangular □ Other
STOREYS  Single Single and Part Cellar Single and Full Basement Two Storeys Two Storeyed Two Storeyed With Part Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron Timber Stud Framed/ Vernacular Timber Stud/Split or Sawn Paling Clad
Windows   □ Original □ Some Later □ All Later □ Leadlight, Stained Glass   □ Timber □ Steel Framed □ All Later □ Leadlight, Stained Glass   □ Original □ Some Later □ All Later □ Leadlight, Stained Glass   □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Threatened by Subdivision □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

FACE BRICK HOUSE, 11 HILTON STREET, MARYBOROUGH.

LOT 9, 10, 14A, SEC. 54B<sup>1</sup>

BUILT:

C.18751 OLDEST PART?

1900S? LOUNGEROOM ADDED?

1928 KITCHEN AND REAR

ADDITIONS<sup>2</sup>

THEMES ILLUSTRATED BY THIS PLACE:

PRIVATE BUILDING -

EDWARDIAN?

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE:

ENTIRE BUILDING AND SITE TO A RADIUS OF 30 METRES

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION





THERE WAS EVIDENTLY A FLOWER MARKET GARDEN IN FRONT OF THIS HOUSE  $^{\rm I}$ 



1928 ADDITIONS

	-	
1	2	2
	<	=
1		2
	Š	2
-	C	0
:		+
-	ä	5
	-	

MANILLA BRIGHT DIVIDERS 5 TAB A4



Ref No: 37100 Made in China www.marbig.com




HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Cellar □ Basement Cellar  WALLS
■ All of the One Basic Material  □ More Than Two Basic Materials □ Original (1) and Later () Section Materials  Walls
Brick - Face
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ■ Excellent □ Good □ Fair □ Substantially Decayed □ Poor □ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Threatened by Subdivision □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

# 20 HOLYROOD STREET,

_																																	
			• •		•		• •			• •	•		• •	• •	• •		•	• •		• •			•	• •	 ٠	 					٠		
M	A	F	5	7	7	F	2	(	7	T	5	(	7	1	1	10	-	1	T														

MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s □ 1900s or 1910s ■ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE    Exploration and
EXTENT OF SIGNIFICANCE Entire Place (Heritage and Site) Including Other Sites  Heritage Item Alone Other  RECOMMENDATION Should be conserved - C  Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architectural Significance  Architect  Architect  Garden Designer  Garden Planting  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Historic Significance  Horticultural Significance  Horticultural Significance  Manufacturing Significance  Streetscape Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual  Unusual Design, Features  Good Quality Design, Features
DESCRIPTION  Place Contains  Main Building  □ Outbuilding/s of Significance □ Garden or Other Structures □ Other □ Ot

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Materials □ Two Basic Materials  Original (1) and Later () Section Materials
Walls       □       Brick - Face       □       Brick - Rendered       □       Brick - Painted Later?       □       Corrugated Iron         □       Brick - Probably Painted       □       Stone       Timber Stud Framed/         □       Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed/         ■       Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       □       Other         Roof (Main Roof (1), Additions (2)-)       □       Pitched       □       Gabled       □       Lean-to       □       Timber Shingles         □       Flat       □       No Eaves       □       Narrow Eaves       □       Canvas         ■       Wide Eaves       □       Slate Cladding       □       Terracotta Tile       □       Flat Metal Sheet         ■       Corrugated Iron       □       Patent Metal Roofing       □       Timber Shingles       □       Metal Deck
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required




City of Maryborough Heritage Study

A. A.

8 5	1101	VDOOD	STREET.
45	H()1	YRUNI	SIRFFI

MARYBOROUGH.				
BUILT   1850s   1900s or 1910   1960s	□ 1860s 0s □ 1920s-1930s □ 1970s	□ 1940s □ 1	1880s or 1890s 1950s 1990s	1908
THEMES IDENTIFIED	BY THIS PLACE			
☐ Exploration and Pastoral Settlement	☐ Gold Discoveries	☐ First Survey as Town Plan	nd Original	Local Government and Growth of the Town
☐ Transport	(Mining and Othe	er) Socio-economi	nic 🗆	Public and
☐ Education	☐ Health	Mix in the Tox	wn	Private Building
□ Religion	☐ Notable Men	☐ Sport and Rec	creation	☐ Victorian
	and Women	☐ Public and Pri	ivate Planting	■ Edwardian □ Inter-war Housing
				☐ Post World War Two
DEGREE OF SIGNIFICA				
EXTENT OF SIGNIFICA		e (Heritage and Site)	_	Other Sites
PEGGA GRAND LOVON	☐ Heritage Ite		□ Other	
RECOMMENDATION	Should be conserved			
	Conservation A	rea		
			market.	
	Annesen			



### CULTURAL SIGNIFICANCE

Significance

☐ Garden or Other

Structures

□ Other

CO	LI UICILI SIGNIFICANT				
Ba	sis of Significance				
	Architectural Significance				
	☐ Architect	□Designer	☐ Builder	☐ Manufacturer of Components	
	☐ Tradesman	☐Garden Design	☐ Garden Plantir	ing Garden Maintenance and Development	
	Associations with Person/9	Group/Body			
	Botanical Significance	☐ Construc	ction Significance	☐ Engineering Significance	
	Historic Significance	☐ Horticul	tural Significance	☐ Landscape Signficance	
	Manufacturing Significand	ce Streetsca	ape Significance	☐ Townscape Significance	
	In Comparison With Othe	r Places in Maryb	orough		
	☐ Typical ☐ Unusual	☐ Unusual Design	n, Features Good	Quality Design, Features Typical Design, Feature	es
DE	ESCRIPTION				
Pla	ace Contains				
	Main Building	☐ Garden	of Significance or Int	nterest	
	☐ Outbuilding/s of	□ Individu	al Planting of Signif	ficance or Building of Significance	

☐ Part of Garden OR ☐ Individually

☐ Other Fences of Significance or Interest

Interest as


☐ Front Fence OR

☐ Buildings of No

Significance

☐ Visible

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  ■ Rectangular □ Other
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS ■ All of the One Basic Material □ Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials
Walls   □ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed   ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction □ Other   Roof (Main Roof (1), Additions (2)-) □ Lean-to □ Timber Shingles   □ Flat □ No Eaves Narrow Eaves □ Canyas
☐ Wide Eaves ☐ Slate Cladding ☐ Terracotta Tile ☐ Flat Metal Sheet ☐ Corrugated Iron ☐ Patent Metal Roofing ☐ Timber Shingles ☐ Metal Deck ☐ Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors
□ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Secondary Elements ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  ☐ In-use ☐ Disused ☐ Abandoned ☐ Threatened by Adjacent Use ☐ Unsympathetic Use ☐ Sympathetic Use ☐ Basic Maintenance ☐ Threatened by Subdivision ☐ Cosmetic Maintenance Required ☐ Threatened by Redevelopment Required



City of Maryborough Heritage Study

Face Brick House Cont.

## CULTURAL SIGNIFICANCE:

This sizeable house is one of the small number of pre 1920 brick houses and residences in Maryborough. The origins of this building are not known, but it appears to be a former farmhouse, in which case it is one of just three pre 1920 brick farmhouses, the others being in Flagstaff Lane and Sebastopol Road.

#### HISTORY:

Original Use:

Farmhouse?

Present Use:

House

Later Owners:

Fuller

The site is understood to have had a commercial orchard north of the house and market gardens in front of it, all now gone.<sup>2</sup> The Fullers moved buildings apparently and two large house-moving wheels survive/survived near the Hilton Street frontage?

## DESCRIPTION:

Style Victorian.

Design standard.

Plan L-shaped.

Single storeyed.

Walls solid face brick - quarried on the site and/or nearby?

Roof hipped, corrugated iron clad.

Features are the verandah and the chimneys, in-ground tank

beneath the loungeroom and flagstone paving surviving from
the demolished stable.

## CONSERVATION GUIDELINES:

Regular maintenance.
When repainting use original/period paint colours and placement.
Ensure all roof and ground-water is collected and taken well
away from the building.

### BIBLIOGRAPHY:

- 1. Maryborough Rate records, Rate notice.
- 2. Information from owner Shirley Coghlin.

City of Maryborough Heritage Study

Schinus areira - PEPPERCORN TREE AND Morus nigra - MULBERRY ? HOLYROOD STREET, MARYBOROUGH.

PLANTED:


CIRCA 1920 (Schinus) CIRCA 1940 (Morus)

DEGREE OF SIGNIFICANCE:

OF LOCAL SIGNIFICANCE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION



## CULTURAL SIGNIFICANCE:

Mature specimens of characteristic trees of rural cities in Victoria. Mulberry is a good specimen relfecting the self sufficient nature of earlier gardens in the city.

## CONSERVATION GUIDELINES:

No perceived threat. Inform owners of value of trees.

City of Maryborough Heritage Study

WEATHERBOARD HOUSE,
3 INKERMAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s 1905? ■ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and  □ Gold Discoveries □ First Survey and Original  □ Local Government  □ And Growth of the Town  □ Transport  □ (Mining and Other) □ Socio-economic □ Public and □ Public and □ Private Building □ Victorian  □ Notable Men  □ Sport and Recreation  □ Notable Men  □ Public and Private Planting □ Inter-war Housing □ Post World War Two
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  ■ Entire Place (Heritage and Site)  □ Heritage Item Alone  □ Other
RECOMMENDATION Should be conserved - C  Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  □ Architect □ Designer □ Builder □ Manufacturer of Components □ Tradesman □ Garden Design □ Garden Planting □ Garden Maintenance and Development □ Associations with Person/Group/Body □ Botanical Significance □ Construction Significance □ Engineering Significance □ Historic Significance □ Horticultural Significance □ Landscape Significance □ Manufacturing Significance □ Streetscape Significance □ Townscape Significance □ In Comparison With Other Places in Maryborough □ Typical □ Unusual □ Unusual Design, Features □ Good Quality Design, Features □ Typical Design, Features
DESCRIPTION  Place Contains

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single Single Single and Part Cellar Single and Full Basement More Than Two Storeys  Two Storeyed Two Storeyed With Part Basement Cellar  Cellar Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials  Original (1) and Later () Section Materials
Walls       □ Brick - Face       □ Brick - Rendered       □ Brick - Painted Later?       □ Corrugated Iron         □ Brick - Probably Painted       □ Stone       Timber Stud Framed/         □ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed/         ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       □ Other         Roof (Main Roof (1), Additions (2)-)       □ Gabled       □ Lean-to       □ Timber Shingles         □ Flat       ■ No Eaves       □ Narrow Eaves       □ Canvas         □ Wide Eaves       □ Slate Cladding       □ Terracotta Tile       □ Flat Metal Sheet         ■ Corrugated Iron       □ Patent Metal Roofing       □ Timber Shingles       □ Metal Deck
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  Intact □ Additions □ Alterations □ Secondary Elements □ Part of the Significance □ Part of the Significance □ Detract from the Significance □ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use Disused Abandoned Threatened by Adjacent Use Unsympathetic Use Sympathetic Use Basic Maintenance Cosmetic Maintenance Required Threatened by Redevelopment Required

## CITY OF MARYBOROUGH HERITAGE STUDY WEATHERBOARD HOUSE, 5 INKERMAN STREET, MARYBOROUGH. BUILT 1850s □ 1860s □ 1870s ☐ 1880s or 1890s 1907? ■ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s THEMES IDENTIFIED BY THIS PLACE Exploration and Gold Discoveries First Survey and Original ☐ Local Government Pastoral Settlement Local Industries Town Plan and Growth of the Town Transport (Mining and Other) Socio-economic ☐ Public and Education ☐ Health Mix in the Town Private Building Religion □ Notable Men ☐ Sport and Recreation ☐ Victorian and Women ☐ Public and Private Planting Edwardian ☐ Inter-war Housing ☐ Post World War Two DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE EXTENT OF SIGNIFICANCE Entire Place (Heritage and Site) ☐ Including Other Sites ☐ Heritage Item Alone □ Other RECOMMENDATION Should be conserved - C Conservation Area

#### **CULTURAL SIGNIFICANCE**

Structures

□ Other

Dania	20	C:~	. :	finana.
Dasis	OI	2151	П	ficance

Das	15 01	Significance							
	Arc	hitectural Significance	;						
		Architect	Design	ner		Builder		Manu	facturer of Components
		Tradesman	□Garde	n Design		Garden Planting	, <b></b>		en Maintenance and Development
	Ass	ociations with Person/	Group/B	ody					***************************************
	Bota	anical Significance		Construct	ion S	Significance		Engine	ering Significance
	Hist	toric Significance		Horticult	ıral S	Significance		Landsca	ape Signficance
	Mai	nufacturing Significand	ce	Streetscap	e Sig	gnificance		Townsc	cape Significance
	In C	Comparison With Othe	r Places	in Marybo	rougl	n			
		Typical   Unusual	<b>Unus</b>	ual Design,	Feat	ires Good Q	uality	Design,	Features   Typical Design, Feature
DES	SCR	IPTION							
Plac	ce C	ontains							
		Main Building		Garden o	f Sign	nificance or Inte	erest		More than One Main
		Outbuilding/s of			-	nting of Signific		or	Building of Significance
		Significance		Interest a		0			Buildings of No
		Garden or Other		☐ Part o	f Gar	den OR 🗆 Indiv	idually	,	Significance

☐ Other Fences of Significance or Interest

☐ Front Fence OR

☐ Visible

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique □ Flat Fronted ■ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials
☐ More Than Two Basic Materials       ☐ Original (1) and Later () Section Materials         Walls       ☐ Brick - Face       ☐ Brick - Rendered       ☐ Brick - Painted Later?       ☐ Corrugated Iron         ☐ Brick - Probably Painted       ☐ Stone       Timber Stud Framed/
□ Vernacular Timber Stud/Split or Sawn Paling Clad
☐ Flat ☐ No Eaves ☐ Narrow Eaves ☐ Canvas ☐ Wide Eaves ☐ Slate Cladding ☐ Terracotta Tile ☐ Flat Metal Sheet ☐ Corrugated Iron ☐ Patent Metal Roofing ☐ Timber Shingles ☐ Metal Deck ☐ Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use

0222			201100011111111111		1021	
WE	AT	HE	RBOARD H	OU	SE,	
			MAN STREE	ΞT,		
BUI	LT		1850s 1900s or 1910s 1960s		1 1860s 1 1920s-1930s 1 1970s	1870s 1940s 1980s
THE	E	xplo			HIS PLACE Gold Discoverie Local Industries	
		rans		_	(Mining and Ot	

g and Other) Education

□ Health ☐ Notable Men

and Women

iscoveries 

First Survey and Original Town Plan

□ 1950s

□ 1990s

☐ 1880s or 1890s

Socio-economic Mix in the Town

☐ Sport and Recreation ☐ Public and Private Planting

Inter-war Housing ☐ Post World War Two

1910?

☐ Local Government

Victorian

Edwardian

☐ Public and

and Growth of the Town

Private Building

DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE Entire Place (Heritage and Site)

☐ Heritage Item Alone

☐ Including Other Sites Other

RECOMMENDATION

Religion

Should be conserved - C



## **CULTURAL SIGNIFICANCE**

## **Basis of Significance**

	Architectural	Significance
--	---------------	--------------

☐ Architect ☐ Tradesman □ Designer ☐Garden Design ☐ Builder ☐ Garden Planting ☐ Manufacturer of Components

☐ Garden Maintenance and Development

☐ Associations with Person/Group/Body

☐ Botanical Significance ☐ Historic Significance

☐ Construction Significance ☐ Horticultural Significance

Engineering Significance ☐ Landscape Signficance

☐ Manufacturing Significance ■ Streetscape Significance

☐ Townscape Significance

In Comparison With Other Places in Maryborough

☐ Typical ☐ Unusual ☐ Unusual Design, Features ☐ Good Quality Design, Features ☐ Typical Design, Features

#### DESCRIPTION

## Place Contains

Main Building

☐ Outbuilding/s of Significance

Garden or Other Structures

☐ Other

☐ Garden of Significance or Interest ☐ Individual Planting of Significance or

Interest as

☐ Part of Garden OR ☐ Individually

☐ Front Fence OR ☐ Other Fences of Significance or Interest

☐ More than One Main

Building of Significance Buildings of No

Significance ☐ Visible

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique □ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single Single and Part Cellar Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials  Original (1) and Later () Section Materials
Walls       □       Brick - Face       □       Brick - Rendered       □       Brick - Painted Later?       □       Corrugated Iron         □       Brick - Probably Painted       □       Stone       Timber Stud Framed/         □       Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed         □       Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       □       Other         Roof (Main Roof (1), Additions (2)-)       □       Pitched       □       Gabled       □       Lean-to       □       Timber Shingles         □       Flat       □       No Eaves       □       Narrow Eaves       □       Canvas         ■       Wide Eaves       □       Slate Cladding       □       Terracotta Tile       □       Flat Metal Sheet         ■       Corrugated Iron       □       Patent Metal Roofing       □       Timber Shingles       □       Metal Deck
Windows   Image: Control of the properties of the prop
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required


# WEATHERBOARD HOUSE,

N.E. CNR. BURNS AND INKERMAN STREETS, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and  □ Gold Discoveries □ First Survey and Original □ Local Government and Growth of the Town □ Transport
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  □ Entire Place (Heritage and Site) □ Heritage Item Alone  □ Other  RECOMMENDATION  Should be conserved - C □ Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Garden Designer  Garden Planting  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Historic Significance  Horticultural Significance  Manufacturing Significance  Streetscape Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual  Unusual Design, Features  Typical Design, Features
DESCRIPTION Place Contains
Main Building       □ Garden of Significance or Interest       □ More than One Main         □ Outbuilding/s of Significance       □ Individual Planting of Significance or Significance       □ Building of Significance         □ Garden or Other Structures       □ Part of Garden OR □ Individually Significance       Significance         □ Other       □ Other Fences of Significance or Interest       □ Visible

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single
□ More Than Two Basic Materials □ Original (1) and Later () Section Materials   Walls □ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone □ Timber Stud Framed/Metal   □ Vernacular Timber Stud/Split or Sawn Paling • Metal Framed   ■ Weatherboard Clad Timber Stud Framed/Metal • amed Construction □ Other   Roof (Main Roof (1), Additions (2)-) □ Lean-to □ Timber Shingles
☐ Flat ☐ No Eaves ☐ Narrow Eaves ☐ Canvas ☐ Wide Eaves ☐ Slate Cladding ☐ Terracotta Tile ☐ Flat Metal Sheet ☐ Corrugated Iron ☐ Patent Metal Roofing ☐ Timber Shingles ☐ Metal Deck ☐ Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors ☐ Original ☐ Serve Later ☐ To All Later ☐ Leadlight, Stained Glass
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

	ı	-	-			8	ı	1	в	5		•	1	-	-	ł	٦	L	١,	A	ē	d		٦	. 1		٧		1	L	,	,		,	υ,	1	L	-	. 1	_	-	ı	7	ı					
۰	•	• •		•		•								٠	•			•	•	•		•	• •								6		•					•	• •						• •		•	٠.	
1	V	1	A		F	2	7	Y	1	F	3	(	1	)]	R	?	(	1	1		T	(	7	1	F	Į																							

BUII	T 🗆	1850s 1900s or 1910 1960s	s [	☐ 1860s ☐ 1920s-1930s ☐ 1970s		1870s 1940s 1980s		1880s o: 1950s 1990s	r 1890s			
THE	MES I	DENTIFIED H	зүт	HIS PLACE								
	_	ration and ral Settlement		Gold Discoverie Local Industries		l First		and Orig	ginal			cal Government I Growth of the Town
	Trans	port		(Mining and Ot)	her)	Socio	-econor	nic			Pub	olic and
	Educa	ation	. 🗆	Health		Mix i	n the T	own				Private Building
	Religi	on		Notable Men and Women		-		ecreation rivate Pla	anting			Victorian Edwardian Inter-war Housing Post World War Two
DEG	REE O	F SIGNIFICA	NCI	E LOCAL SIGN	IIFIC	ANCE					П	rost world war I wo
EXT	ENT O	F SIGNIFICA ENDATION	NCI	E Entire Pla  Heritage l  hould be conserved	ice (H Item A	eritage a	and Site	e) 🗆	Includ Other	ing	Othe	er Sites
		155 64 - 5 (Val. 74 (d. 15)		Conservation	Area		A BHY GO	The Back				1 - 4 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -



# CULTURAL SIGNIFICANCE

Architectural Significance  ☐ Architect	□ Designer		Builder		Manufacturer of Components
☐ Tradesman	☐Garden Design		Garden Planting		Garden Maintenance and Development
Associations with Person/0	Group/Body				•
Botanical Significance	☐ Construc	tion S	Significance		Engineering Significance
Historic Significance	☐ Horticult	ural S	Significance		andscape Signficance
Manufacturing Significand	ce Streetsca	pe Sig	gnificance		Townscape Significance
In Comparison With Other	Places in Marybo	roug	h		
☐ Typical ☐ Unusual	Unusual Design	, Feat	ures Good Qu	uality l	Design, Features   Typical Design, Feature

## Plac

	di Hon			
e C	Contains			
	Main Building	Garden of Significance or Interest		More than One Main
	Outbuilding/s of	Individual Planting of Significance or		Building of Significance
	Significance	Interest as		Buildings of No
	Garden or Other	☐ Part of Garden OR ☐ Individually		Significance
	Structures	Front Fence OR		☐ Visible
	Other	☐ Other Fences of Significance or Interes	st	

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique □ Flat Fronted ■ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single Single and Part Cellar Single and Full Basement Two Storeys  Two Storeyed Two Storeyed With Part Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
□ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
☐ Wide Eaves ☐ Slate Cladding ☐ Terracotta Tile ☐ Flat Metal Sheet ☐ Corrugated Iron ☐ Patent Metal Roofing ☐ Timber Shingles ☐ Metal Deck ☐ Tiles
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use

1 -

BRICK AND WEATHERBOARD RESIDENCE, 20 INKERMAN STREET, MARYBOROUGH.

SEE FOLLOWING EVALUATION FOR THE TREES.

(CA PT.6 SECT. 44A)

BUILT:

1875 BRICK SECTION<sup>2</sup>

1877 BRICK AND WOOD

HOUSE<sup>2</sup>

EARLY 20TH CENTURY? REAR WEATHERBOARD ADDITIONS

THEMES ILLUSTRATED BY THIS PLACE:

SOCIO-ECONOMIC MIX IN THE

TOWN

PRIVATE BUILDING -

VICTORIAN

LOCAL INDUSTRIES

(PRINTING)

GROWTH OF TOWN (CHURCHES)

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE:

ENTIRE BUILDING AND SITE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION

CONSERVATION AREA: MARYBOROUGH WEST



Brick and Weatherboard Residence Cont.

## CULTURAL SIGNIFICANCE:

This brick and weatherboard dwelling constructed in 1875<sup>2</sup> or earlier, <sup>1</sup> has historical significance as one of the oldest surviving 19th century residences in the City. Built in two stages this residence was associated with a number of significant Maryborough people including George Edwards, printer, in the 1870s; <sup>2</sup> James B. Crooks, leather merchant, in the World War I period; <sup>3</sup> and Charles Young, clergyman, in the early 1920s. At this time the building was used as the manse <sup>4</sup> for the Church of Christ's Christian Church on the corner of Inkerman and Clarendon Streets, Maryborough (q.v.). Comparatively few pre 1920 Maryborough houses were built in two stages and this building is an interesting combination of 19th century cottage and substantial rear additions probably of the early 20th century. The difference in scale between the two sections reflects the incresing permanence of Maryborough and aspirations of its residents, as well as changes in architectural taste.

## HISTORY:

Original and Later Use:

Use from 1919-1923:

Original Owner:

Later Owners:

Private residence.

Church of Christ manse.<sup>4</sup>

George Middleton, miner?<sup>1</sup>

1870s-c.1900 George Edwards, printer.<sup>2</sup> (Possibly the original owner.)

C.1912-1914 Sarah Edwards<sup>6</sup>

1914- James B. Crooks, leather merchant.<sup>3</sup>

1919-c.1923 Charles Young, clergyman, 4

1923-post 1936 James Paterson, railway employee.

Brick and Weatherboard Residence Cont.

During the 1870s, a wooden house, NAV £10, owned by George Edwards, printer, stood in allotment six, section 44A, in Carlyle (Inkerman) Street<sup>9</sup> - the site of the present brick and weatherboard house at 20 Inkerman Street. From 1875, it was described as a clay brick house, NAV £8,<sup>2</sup> and then, in 1877, as a brick and wood house, NAV £12.<sup>2</sup> George Edwards owned the property until the turn of the century when it was described as a brick house, NAV £20.<sup>10</sup> Sarah Edwads was its owner in 1912.<sup>6</sup> The rear weatherboard section probably dates from this period.

The house passed out of the hands of the Edwards family by 1914 when it was owned and occupied by James B. Crooks, leather merchant.<sup>3</sup> From 1919 until circa 1923 it was owned by the Trustees of the Church of Christ and used as the manse for the Christian Church in Maryborough. It was occupied by Charles Young, clergyman.<sup>4</sup> The Church of Christ was established in Maryborough in 1862 and became the headquarters for a mission which covered a large area including Mariner's Reef, Maryborough, Carisbrook, Alma, Chinaman's Flat and Havelock. The first full-time preacher was appointed in 1865 and in 1867 the Christian Disciples bought land on the corner of Inkerman and Clarendon Streets in Maryborough. They erected a church there known as the Christian Church.<sup>5</sup> The next owner/occupier of the brick and weatherboard dwelling in Inkerman Street was James Paterson, a railway employee, in 1923.<sup>7</sup> By this time the property had an NAV of £25. Paterson was the owner/occupier still in 1936.<sup>11</sup>

### **DESCRIPTION:**

### Brick Front Section

Style mid Victorian.

Design standard.

Single storeyed.

Walls solid brick.

Roof gabled with shallow eaves, corrugated iron.

Features are the encircling timber verandah with its small cast iron frieze and brackets and the modest size of the building.

## Weatherboard Rear Section

Style late Victorian/Edwardian. Design standard. Plan rectangular. Single storeyed. Brick and Weatherboard Residence Cont.

Walls timber stud construction, weatherboard clad.
Roof hipped with shallow eaves, corrugated iron clad.
Features are the size and height of the addition in relation to the brick front section and the chimneys.

### **BIBLIOGRAPHY:**

- 1. Maryborough RB 1865 No.429.
- 2. Ibid. 1875 No.337; Ibid. 1877 No.280.
- 3. Ibid. 1914-15 No.1407.
- 4. Ibid. 1920-21 No.1331 (the previous year "manse" written in).
- 5. Osborn and DuBourg, Maryborough, pp.146-147.
- 6. Maryborough RB 1912-13 No.1417.
- 7. Ibid. 1923-24 No.1352.
- 8. Ibid. 1869 No.317.
- 9. Ibid. 1873 No.328.
- 10. Ibid. 1905-6 No.1395.
- 11. Ibid. 1936-37 No.1648 (Listed in allotment six, section 44A and numbered 97 Inkerman).

## CONSERVATION GUIDELINES:

Regular maintenance as necessary.

Collect all roof and ground-water and carry well away from the building.

When repainting use original/period paint colours.

Chemically remove paint from face brick walls to return to most probably original appearance.

Ulmus procera - ENGLISH ELM AND Schinus areira - PEPPERCORN, 20 INKERMAN STREET, MARYBOROUGH.


PLANTED:

CIRCA 1920

DEGREE OF SIGNIFICANCE: OF LOCAL SIGNIFICANCE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION



## CULTURAL SIGNIFICANCE:

Remnant property boundary planting of two fine mature trees. They contribute to the locality and make an effective skyline.

Ulmus procera and Schinus areira Cont.

# CONSERVATION GUIDELINES:

No apparent threat. Inform owners of value of trees.

Som: 
By having this information it should clear up any ambiguities for the future.

Cach time the Advertises' cites

No 26, the paper reports that Robert Hubble bruilt it (untrue) and lived in it (untrue, as he died 1902.)

Dorothy Whitmore

WEATHERBOARD HOUSE, 26 INKERMAN STREET, MARYBOROUGH.

(CA PT.12 SECT. 44)

BUILT:

1888<sup>1</sup>

1900s VERANDAH (AND

ADDITIONS?)

THEMES ILLUSTRATED BY THIS PLACE:

SOCIO ECONOMIC MIX IN THE

TOWN

PRIVATE BUILDING -

VICTORIAN

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE


EXTENT OF SIGNIFICANCE:

ENTIRE BUILDING AND SITE


**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION

CONSERVATION AREA - MARYBOROUGH WEST







Weatherboard House Cont.

## CULTURAL SIGNIFICANCE:

This unusual weatherboard residence in Inkerman Street (known earlier as Carlyle Street) has both historical and architectural significance. It was the home for 14 years of Robert Hubble (1816-1902) a carpenter from Kent and the founder of an important local firm, Hubble and Sons, a well-known carpentry, undertaking, and house-shifting business.<sup>2</sup> Built in 1888<sup>1</sup> on his retirement from the family firm, Hubble lived in his Inkerman Street residence until his death in 1902. The building itself is an unusual one for Maryborough, due to the fusion of 19th and early 20th century sections and the continuation of the main roof over the encircling verandahs. The modest scale of this building typifies the homes of most of Maryborough's settlers during the 1850s, 1860s, 1870s and 1880s.

HISTORY:

Original and Later Use:

Private residence.

Original Owner:

1888-1902 Robert Hubble,

carpenter.1

Later Owners:

1902-1910 Eliza

Hubble<sup>3</sup>

1910-1919 Daisy

Kuffer<sup>4</sup>

1919- Charles Kuffer.

railway employee<sup>5</sup>

Builder/Artisan:

Robert Hubble?

Robert Hubble, carpenter, was rated for the first time in 1888 for a wood house, NAV £25, in Carlyle Street 1 (the earlier name for the southern part of Inkerman Street). He was there until his death in 1902.6

Robert Hubble was born on the 13 April 1816 at Tunbridge, Kent. He was a carpenter, who worked at the British Museum for 8 years. Hubble arrived in Port Fairy in January 1855 and came to the Alma Diggings near Maryborough in 1856. In 1858 he began working as a carpenter in Edward Harkness's shop, and later opened a furniture shop. Hubble then conducted a carpentry, undertaking, and house-shifting business until 1887 when he retired and handed the business over to his sons - Robert, John and William. John was manager of the family business for 60 years.2

Weatherboard House Cont.

Robert Hubble, Sen. was listed as owner/occupier of the Inkerman Street house for the last time in 1902 when it had an NAV of £20.6 The following year, Eliza Hubble was listed as owner/occupier.3 She was there still in 1909. By this date, the Hubble Estate owned two adjacent properties, a wood house (NAV £16) and a stone house (NAV £10).7 Daisy Kuffer was the new owner of Robert Hubble's weatherboard house in 1910,4 followed by Charles Kuffer, railway employee, in 1919.5 Charles Kuffer was there still in 1936, when the property had an NAV of £14.8

### DESCRIPTION:

Style fusion of late Victorian and Edwardian.
Design one-off.
Plan L-shaped.
Single storeyed.
Walls timber stud construction, weatherboard clad.
Roof hipped and continuous with the encircling verandah, corrugated iron clad.
Features are the encircling Edwardian timber verandah, L-shape, front bay window, chimney and modest size.

## BIBLIOGRAPHY:

- 1. Maryborough RB 1888 No.1100.
- 2. Osborn and DuBourg, Maryborough, pp.290, 293, 368, 372.
- 3. Maryborough RB 1903-4 No.1346.
- 4. Ibid. 1910-11 No.1428.
- 5. Ibid. 1919-20 No.1332.
- 6. Ibid. 1902-3 No.1332.
- 7. Ibid. 1909-10 Nos.1409, 1410, 1411.
- 8. Ibid. 1936-37 No.1651.

## CONSERVATION GUIDELINES:

Regular maintenance as necessary.

Stop rust on roof iron sheets.

When repainting use original (Edwardian or Victorian)/period paint colours and placement.

Ensure all roof and ground-water is carried well away from the building.

Erect original/appropriate period front fence.

24 Burns Street
Maryborough 3465

Attention Mr. Norm. Cameron.

Re houses listed in the Heritage Study.

The house at No. 28 Inkerman Street was built by the late Robert Hubble (a former Mayor of Maryborough) for his retirement, in 1887.

He named it 'Kent Villa' after his birthplace in Tunbridge, Kent, England.

This house, which became 'Kentville', was occupied by his descendants until the early 1970's when it was sold.

The house on the corner, No. 26 Inkerman Street, was transported from Havelock and settled on the corner of the 'Kentville' block in 1918. This was a one-bedroomed cottage.

A diary recorded by Robert Hubble's grandson, Les Kuffer details the re-erection of this house.

Les Kuffer acquired 'Kentville' prior to his marriage, and prepared No. 26 for his widowed Mother's occupation.

Excerpts from his diary include:

Friday, September 27th. 1918 'Havelock, re house.'

October 2nd. 'House down' on block.

October 11th. 'Gutters made' (spouting)


'Painting' and 'Fence' are regularly mentioned.

December 14th. 'TUAGGRA sign painted.' the house was named 'TUAGGRA' by his Mother as she was born in Tuaggra Street, Maryborough.

Dorothy Whitmore

Dorothy Whitmore

A great-grand-daughter of Robert Hubble



Basis of	Significance							
Arch	itectural Significance	9						
	Architect	Design	ner		Builder		Manufa	acturer of Components
	Tradesman	□Garde	en Design		Garden Planting			Maintenance and Development
☐ Asso	ciations with Person/	Group/B	Body					•
□ Bota	nical Significance		Construction	n S	Significance		Engineer	ring Significance
☐ Histo	oric Significance				Significance		-	e Signficance
□ Man	ufacturing Significan	ce	Streetscape		_		-	pe Significance
In C	omparison With Othe	r Places	in Maryboro	ugh	n			
□ T	ypical Unusual	Unus	sual Design, F	eati	ires Good Q	uality	Design, F	eatures   Typical Design, Feature
DESCRI	PTION							
Place Co	ntains							
	Main Building		Garden of S	Sign	nificance or Inte	rest		More than One Main
	Outbuilding/s of		Individual 1	Plai	nting of Signific	ance	or	Building of Significance
	Significance		Interest as					Buildings of No
	Garden or Other		☐ Part of	Gar	den OR 🗆 Indivi	dually		Significance
	Structures		Front Fence	e O	R			☐ Visible
	Other		□ Other F	ence	es of Significance	or Int	erest	

**CULTURAL SIGNIFICANCE** 

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN?
DESIGN  ■ Standard □ One-off □ Unique □ Flat Fronted ■ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
Pitched □ Gabled □ Lean-to □ Timber Shingles □ Flat □ No Eaves □ Narrow Eaves □ Canvas □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet □ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck □ Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass
☐ Timber ■ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  Intact □ Additions □ Alterations □ Secondary Elements □ Part of the Significance □ Part of the Significance □ Detract from the Significance □ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use



City of Maryborough Heritage Study

# BRICK AND WEATHERBOARD RESIDENCE,

30 INKERMAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s ■ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries □ Town Plan □ Local Government and Growth of the Town □ Transport □ (Mining and Other) □ Socio-economic □ Public and □ Private Building □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing □ Post World War Two
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  ☐ Heritage Item Alone  ☐ Other  RECOMMENDATION  Should be conserved - C  ☐ Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect □Designer □ Builder □ Manufacturer of Components □ Tradesman □Garden Design □ Garden Planting □ Garden Maintenance and Development □ Associations with Person/Group/Body □ Botanical Significance □ Construction Significance □ Engineering Significance □ Historic Significance □ Horticultural Significance □ Landscape Significance □ Manufacturing Significance □ Streetscape Significance □ Townscape Significance □ In Comparison With Other Places in Maryborough □ Typical ■ Unusual □ Unusual Design, Features □ Good Quality Design, Features □ Typical Design, Features
DESCRIPTION  Place Contains   Main Building  Garden of Significance or Interest  Under than One Main  Individual Planting of Significance or Building of Significance  Significance  Interest as  Under Fence or Interest  Structures  Other  Other  Other Fences of Significance or Interest  Other Fences of Significance or Interest

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN AND 1919?
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  ■ Rectangular □ Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS □ All of the One Basic Material □ Two Basic Materials □ More Than Two Basic Materials □ Original (1) and Later () Section Materials
Walls   Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed   ■ Weatherboard Clad Timber Stud/Framed/Metal Stud Framed Construction □ Other   Roof (Main Roof (1), Additions (2)-) Pitched □ Gabled □ Lean-to □ Timber Shingles   □ Flat □ No Eaves ■ Narrow Eaves □ Canvas   □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet   ■ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Threatened by Subdivision □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

WEATHERBOARD RESIDENCE, 31 INKERMAN STREET, MARYBOROUGH.

DEGREE OF SIGNIFICANCE:

BUILT: BETWEEN 1887 AND 1891

THEMES ILLUSTRATED BY THIS PLACE: SOCIO ECONOMIC MIX IN THE

TOWN

PRIVATE BUILDING -VICTORIAN

EXTENT OF SIGNIFICANCE: ENTIRE BUILDING AND SITE


RECOMMENDATIONS: REGISTER OF THE NATIONAL

**ESTATE** 


LOCAL PLANNING PROTECTION

CONSERVATION AREA - MARYBOROUGH WEST

LOCAL SIGNIFICANCE







origina oum

Weatherboard Residence Cont.

GATUARD, TAFFORZ GATUARD & DIMPUSSO (DIMMENSS)

## CULTURAL SIGNIFICANCE:

This dwelling was one of two built between 1887 and 1891 for and by John Salmon Carpenter¹ and most probably designed by Architect W.G. Kell⁶ (see 29 Park Road). Designwise this building illustrates the latest in decoration using timber instead of previously popular cast iron. This building is also an illustration of the importance of the building trade and building artisans during the 1880s building boom in Maryborough, a major Victorian goldfields town. Buildings of this size are rare in Maryborough and in this part of the City. With nos. 7 and 29 Park Road, this residence is architecturally the finest 19th century timber dwelling in the Municipality. It illustrates the sort of elaborate residence that only a small number enjoyed in Maryborough during the 19th and early 20th centuries, due principally to the local economy not being a rich one despite the gold mines, which sent their profits away from Maryborough to the sources of their capital.

HISTORY:

Original and Later Use:

Private residence.

Oiginal Owner:

1887-1891 John Salmon,

carpenter.1

Later Owner:

By 1896- Isaac

Harris<sup>2</sup>

Architect:

William G. Kell<sup>6</sup>

Builder/Artisan:

John Salmon

In 1887, John Salmon, carpenter, owned a wood house in Carlyle Street, NAV £10 and a block of vacant land.¹ By 1891, Salmon was the owner of two timber houses, one occupied by himself with an NAV of £18 and a new building (NAV £25) occupied by Charles Miller, clerk.¹ Walter Boyes, miller, lived in the new house in 1896 when it was owned by Isaac Harris.² Salmon was owner/occupier still of the other wood house, NAV £18. Boyes was still in the new house in 1900, when it was owned still by Harris.⁴ By 1910 Harris owned both timber houses, letting one to William Harris, butcher, and the other to William Henderson, railway employee.⁵

Weatherboard Residence Cont.

## DESCRIPTION:

Style late Victorian.

Design decoration one-off, residence design standard.

Plan rectangular.

Single storeyed.

Walls timber stud construction, weatherboard clad.

Roof hipped with one front gable and shallow eaves, corrugated iron clad.

Features are the verandah with its perforated timber decoration, front gable with decorated fascias and infil, eaves with festoons set in a lozenge shaped frame, with roundells and

elaborate consoles, chimneys and cast iron ridge cresting.

## BIBLIOGRAPHY:

- Maryborough RB 1887 Nos. 818, 819; Ibid. 1891 Nos. 1182, 1183.
- 2. Ibid. 1896 No. 1298
- 3. Ibid. No. 1299.
- 4. Ibid. 1900 Nos. 1278, 1279.
- 5. Ibid. 1910-11 Nos. 1400, 1401.

## CONSERVATION GUIDELINES:

Regular maintenance as necessary.

Erect original/appropriate period front fence.

Lay out and plant front garden to suit the period of the building.

# WEATHERBOARD HOUSE,

32 INKERMAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and  □ Gold Discoveries □ First Survey and Original □ Local Government and Growth of the Town □ Transport
DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE  EXTENT OF SIGNIFICANCE ■ Entire Place (Heritage and Site) □ Including Other Sites □ Heritage Item Alone □ Other  RECOMMENDATION Should be conserved - C □ Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect
DESCRIPTION  Place Contains   Main Building  Garden of Significance or Interest  Under than One Main  Dutbuilding/s of Significance  Individual Planting of Significance or Significance  Interest as Under Structures  Part of Garden OR □ Individually Structures  Pront Fence OR Uniterest  Visible  Other Fences of Significance or Interest

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single
All of the One Basic Material  ☐ Two Basic Materials ☐ Original (1) and Later () Section Materials  Walls
□ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use

WEAT	HE	RBOARD HO	OUS	Ε,	
34 INI	KEF	RMAN STREE	ET		
MARYE	BOR	OUGH.			
BUILT		1850s		1860s	1870s
		1900s or 1910s		1920s-1930s	1940s
		1960s		1970s	1980s

#### THEMES IDENTIFIED BY THIS PLACE

F 1 1	C 11D: .		F: . C 10:: 1	· ·	1.0
Exploration and	Gold Discoveries		First Survey and Original	Lo	cal Government
Pastoral Settlement	Local Industries		Town Plan	and	Growth of the Town
Transport	(Mining and Other	r) 🗆	Socio-economic	Pub	olic and
Education	Health		Mix in the Town		Private Building
Religion	Notable Men		Sport and Recreation		Victorian
	and Women		Public and Private Planting		Edwardian
					Inter-war Housing
					Post World War Two

☐ 1880s or 1890s

□ 1950s

□ 1990s

## DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE Entire Place (Heritage and Site) ☐ Including Other Sites □ Other

☐ Heritage Item Alone Should be conserved - C

Conservation Area



## **CULTURAL SIGNIFICANCE**

Structures

□ Other

RECOMMENDATION

Bas	sis of Significance					
	Architectural Significance					
		□Designer		Builder		Manufacturer of Components
	☐ Tradesman	□Garden D	Design $\square$	Garden Planting		Garden Maintenance and Development
	Associations with Person/G	roup/Bod	y			
	Botanical Significance	$\Box$ C	Construction S	Significance		Engineering Significance
	Historic Significance	$\Box$ H	Iorticultural S	Significance		Landscape Signficance
	Manufacturing Significance	e 🗆 St	treetscape Sig	gnificance		Townscape Significance
	In Comparison With Other	Places in	Maryborough	h		
	☐ Typical ☐ Unusual □	☐ Unusual	l Design, Feat	ures 🛮 Good Q	uality l	Design, Features 📕 Typical Design, Feature
DE	SCRIPTION					
Pla	ce Contains					
	Main Building	□ G	Garden of Sign	nificance or Inte	rest	☐ More than One Main
	☐ Outbuilding/s of	□ Ir	ndividual Pla	nting of Signific	ance o	or Building of Significance
	Significance	Ir	nterest as			☐ Buildings of No
	☐ Garden or Other		Part of Gar	den OR 🗆 Indivi	dually	Significance

☐ Other Fences of Significance or Interest

☐ Visible

☐ Front Fence OR

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE CALIFORNIAN BUNGALOW
DESIGN  ■ Standard □ One-off □ Unique □ Flat Fronted ■ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single Single and Part Cellar Single and Full Basement Two Storeys Two Storeyed Two Storeyed With Part Basement Cellar  Cellar Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials Original (1) and Later () Section Materials
Walls   □ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed/   ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction □ Other   Roof (Main Roof (1), Additions (2)-) □ Pitched □ Gabled □ Lean-to □ Timber Shingles   □ Flat □ No Eaves □ Narrow Eaves □ Canvas   ■ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet   ■ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck   Tiles
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use Disused Abandoned Threatened by Adjacent Use Unsympathetic Use Sympathetic Use Basic Maintenance Threatened by Subdivision Cosmetic Maintenance Required Threatened by Redevelopment Required

RENDERED BRICK RESIDENCE, 35 INKERMAN STREET, MARYBOROUGH.

BUILT: 1949<sup>1</sup>

THEMES ILLUSTRATED BY THIS PLACE: SOCIO ECONOMIC MIX IN THE

TOWN

PRIVATE BUILDING - POST

SECOND WORLD WAR


DEGREE OF SIGNIFICANCE: LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE: ENTIRE BUILDING, FRONT

FENCE AND SITE

RECOMMENDATIONS: LOCAL PLANNING PROTECTION

CONSERVATION AREA - MARYBOROUGH WEST



Rendered Brick Residence Cont.

#### CULTURAL SIGNIFICANCE:

This residence is one of just two examples in Maryborough of conventionally designed 1930s-1950s rendered brick residences, the other being at 34 Palmerston Street. Though both are a little behind the times, they show the continuation of building styles in country towns after they have lost their popularity in Melbourne. Though very different from its peers architecturally, this building forms part of a recommended conservation area with a predominance of average 19th century and 1900s-1920s houses juxtaposed with the odd grander residence and non-residential building. Number 31 is an 1890s version of this building. The reasons for there being just two examples in Maryboorugh are the economic situation then, which has affected every decade of town's history, combined with the shortages of building materials following the Second World War. There are also two streamlined, similar houses at 20 Goldsmith Street (1952) and 27 Wellington Street (1950).

#### HISTORY:

Original and Continuing Use:

Residence

## DESCRIPTION:

Style 1930s-1950s streamlined.

Design on-off.

Plan basically rectangular with projecting garage.

Single storeyed.


Walls solid brick? rendered.

Roof hipped with eaves, terracotta tile clad.

Features are the quarter circle window with a stepped parapet, flat-roofed entry porch, chimney and flat-roofed garage.

## CONSERVATION GUIDELINES:

Regular maintenance as necessary.
When repainting use period/appropriate paint colours and placement.



A.

City of Maryborough Heritage Study

Significance

☐ Garden or Other

Structures

□ Other

Interest as

☐ Front Fence OR

☐ Part of Garden OR ☐ Individually

☐ Other Fences of Significance or Interest

WEATHERBOARD HOUSE,
36 INKERMAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s □ 1900s or 1910s ■ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and   □ Gold Discoveries □ First Survey and Original   □ Local Government
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  □ Heritage Item Alone  □ Other  RECOMMENDATION  Should be conserved - C  □ Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Designer  Garden Planting  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Historic Significance  Horticultural Significance  Horticultural Significance  Manufacturing Significance  Streetscape Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual Design, Features
DESCRIPTION  Place Contains   Main Building □ Garden of Significance or Interest □ More than One Main  Outbuilding/s of □ Individual Planting of Significance or Building of Significance

☐ Buildings of No

Significance ☐ Visible

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE CALIFORNIAN BUNGALOW
DESIGN  ■ Standard □ One-off □ Unique □ Flat Fronted ■ Double Fronted □ More Than Two Fronts □ Other
PLAN Rectangular  Other
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS
☐ All of the One Basic Material ☐ Two Basic Materials ☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials ☐ Walls
□ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck Tiles  Windows □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight Stained Glass
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required □ Threatened by Redevelopment Required

BRICK RESIDENCE, 37 INKERMAN STREET, MARYBOROUGH.

(CA PT.22 SECT. 42)

BUILT:

1902<sup>1</sup>

1990S REAR ADDITION

THEMES ILLUSTRATED BY THIS PLACE:

SOCIO ECONOMIC MIX IN THE

TOWN

PRIVATE BUILDING - INTER-WAR YEARS

NOTABLE MEN AND WOMEN

(DOCTORS)

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE:

ENTIRE BUILDING AND SITE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION

CONSERVATION AREA: MARYBOROUGH WEST



Brick Residence Cont.

## CULTURAL SIGNIFICANCE:

This Edwardian brick residence has historical significance for its associations with Dr. R.H. Dunn, House Surgeon at the Maryborough Hospital from 1858 until 1901 and consulting surgeon at the hospital from then until his death in 1905. Dunn was a major figure in the medical history of the town from its goldrush origins and reportedly "ruled the hospital like a monarch ruling his Kingdom." His residence, one of the small number of pre 1920 brick dwellings in Maryborough, illustrates the sort of building lived in by a prominent local doctor/surgeon.

#### HISTORY:

Original and Later Use:

Private residence.

Original Owner:

1902-1905 Dr. R.H. Dunn,

surgeon.1

Later Owners:

1905-c.1914 Charlotte Dorman<sup>4</sup>

C.1914-1921 Isaac

Harris<sup>5</sup>

1921-1923 Miss E.

Harris<sup>6</sup>

1923 - Mary Galloway<sup>7</sup>

1925-1926 Miss Anne Charlotte Harse<sup>8</sup>

1936-1937 Eileen

O'Rea9

Later Occupants:

1924 George Patience<sup>13</sup>

In 1901, Dr. R.H. Dunn, surgeon, purchased an allotment of land in Carlyle Street (the earlier name for the southern part of Inkerman Street) from H.N. Phillips, Maryborough's town clerk. $^{10}$  The following year, Dr. Dunn was rated for a brick house there with an NAV of £25. $^1$  He was listed as the owner/occupier of this residence until his death in 1905.11

Brick Residence Cont.

Dr. Dunn graduated from Dublin University in 1856 and sailed for Australia after obtaining his MRCS. In 1857, he came to the gold town of Maryborough, where he practised as a surgeon until his death. In 1858, Dunn was appointed House Surgeon at the new Maryborough Hospital, a position he retained until he resigned in 1901. This was the year he purchased the site of his Carlyle (Inkerman) Street house. After 1901, Dunn was appointed consulting surgeon (non-resident) at the hospital, a position he held until his death on 16 October 1905. Dunn was heavily involved in local affairs. He was Captain of the Volunteer Rifles, held important masonic offices, was a J.P. and, in 1871, was President of the Maryborough Harmonic Society. Dunn was a leading figure in the medical life of the town and reputedly "ruled the hospital like a monarch ruling his Kingdom." Kingdom."

After Dunn's death, his brick residence in Carlyle (Inkerman) Street became the property of Charlotte Dorman<sup>4</sup> and, by 1914, of Isaac Harris. During Harris' ownership, the house was let to William Land, miller, and Arthur Hugh Gough, a Post Office clerk. Miss E. Harris became the new owner in 1921, when the NAV had risen to £40.6 By 1923, however, another new owner was recorded, Mary Galloway.' The following year, when the house was owned by the Mary Galloway Est., it was occupied by the local manufacturer, George Patience. <sup>13</sup> In that year, Patience established his new company, Patience and Nicholson, in the town and the following year, 1925, moved into his new brick residence, now known as 46 Palmerston Street. Miss Anne Charlotte Harse was recorded as the owner/occupier of the Carlyle Street residence in the 1925-26 Maryborough rate book.8 Charlotte Harse was there still in 1933.14 In the 1936-37 rate book, Eileen O'Dea was listed as the owner/occupier of the brick house in allotment part 22, section 42 (the site of 37 Inkerman Street), NAV £40, described as 88 Inkerman Street.9

#### DESCRIPTION:

Style late Victorian.

Design standard.

Plan rectangular.

Single storeyed.

Walls solid face brick.

Roof hipped with shallow eaves, corrugated iron clad.

Features are the symmetrical front elevation, front verandah and chimneys.

- 4 -

Brick Residence Cont.

## BIBLIOGRAPHY:

- 1. Maryborough RB 1902-3 No.1307.
- Osborn and DuBourg, Maryborough, pp.155, 170, 173, 179, (illustration photography p.179), 359.
- Ibid. p.340.
- 4. Maryborough RB 1909-10 No.1385 (NAV £25).
- Ibid. 1914-15 No.1385 (NAV £25). 5.
- 6. Ibid. 1921-1922 No.1320 (NAV £40).
- Ibid. 1923-1924 No.1332 (NAV £40).
- 8. Ibid. 1925-1926 No.1352 (NAV £40). 9. Ibid. 1936-1937 No.1624 (NAV £40). 10. Ibid. 1901-1902 No.1292 (NAV £4). 11. Ibid. 1905-1906 No.1373.

- 12. Ibid. 1919-1920 No.1308.
- 13. Ibid. 1924-1925 No.1348.
- 13. Ibid. 1933-1934 No.1458.

## CONSERVATION GUIDELINES:

Regular maintenance as necessary. Repair cement render to chimneys. Chemically remove paint to avoid having to repaint.

## DESCRIPTION

#### **Place Contains**

Main Building	Garden of Significance or Interest
Outbuilding/s of	Individual Planting of Significance
Significance	Interest as

Garden or Other		Part of	Garden	OR	Individual
	the second second				

Structures Front Fence OR □ Other

cance or

☐ Other Fences of Significance or Interest

☐ More than One Main

Building of Significance

Buildings of No Significance

☐ Visible

□ Yes □ No
USE  ☐ Present Use Same as Original ☐ Different Original Use ☐ Known Later Use or Interest
STYLE 1920S
DESIGN  ☐ Standard ☐ One-off ☐ Unique ☐ Flat Fronted ☐ Double Fronted ☐ More Than Two Fronts ☐ Other
PLAN  Rectangular  Other
STOREYS  Single Single and Part Cellar Single and Full Basement Two Storeys Two Storeyed Two Storeyed With Part Basement Cellar  Cellar Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
Brick - Face
Windows  Original Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors  Original Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

# WEATHERBOARD HOUSE,

WEATHERBOARD HOUSE,
41 INKERMAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s ■ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and  □ Gold Discoveries □ First Survey and Original □ Local Government and Growth of the Town □ Transport
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  ☐ Entire Place (Heritage and Site) ☐ Including Other Sites ☐ Heritage Item Alone ☐ Other
RECOMMENDATION Should be conserved - C  Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Garden Designer  Garden Planting  Garden Manufacturer of Components  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Construction Significance  Historic Significance  Horticultural Significance  Manufacturing Significance  Streetscape Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual  Unusual Design, Features
DESCRIPTION  Place Contains   Main Building  □ Garden of Significance or Interest □ More than One Main □ Outbuilding/s of □ Significance □ Individual Planting of Significance or □ Significance □ Part of Garden OR □ Individually □ Structures □ Front Fence OR □ Other □ Other □ Other Fences of Significance or Interest

HISTORY KNOWN  ☐ Yes  No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN Rectangular  Other
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full □ Cellar □ Basement Cellar
☐ All of the One Basic Material ☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
□ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Threatened by Subdivision □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

WEATHERBOARD RESIDENCE, 42 INKERMAN STREET, MARYBOROUGH.

(CA PT. LOT 13 SECT. 45)

BUILT:

1893<sup>1</sup>

THEMES ILLUSTRATED BY THIS PLACE:

PRIVATE BUILDING -

VICTORIAN

NOTABLE MEN AND WOMEN (OGLE FAMILY CHEMISTS)

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE:

ENTIRE BUILDING AND SITE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION

CONSERVATION AREA - MARYBOROUGH WEST



Weatherboard Residence Cont.

## CULTURAL SIGNIFICANCE:

This 1893 weatherboard residence built for Samuel G. Gaylord, draper, has historical significance for its associations with a number of successful local businessmen. From the turn of the century until the early 1920s it was owned by the Ogle family, notable Maryborough chemists. This family played a prominent role in the early history of Maryborough from the 1850s and from that time owned a shop in High Street, the town's commercial centre. The building is typical of many similar dwellings in Maryborough.

#### HISTORY:

Original and Later Use:

Original Owner:

Private residence.

1893-1902 Samuel G. Gaylord, draper.<sup>1</sup>

1902 John F. Ogle, chemist.<sup>2</sup>

1919-1920 Mrs. Agnes Ogle<sup>6</sup>

-1921 John F. Ogle, chemist. $^3$ 

1921- Reginald Kennedy, machinist.

Early 1930s- John Duncan, engine driver.8

In 1892, Samuel G. Gaylord, draper, owned the site of the weatherboard house known now as 42 Inkerman Street, listed then as vacant land. The following year, a wooden house owned and occupied by Gaylord was listed in the Maryborough rate books with an NAV of £30. Gaylord was associated with another weatherboard house at 33 Inkerman Street, which was built for him in 1897. By that date, Gaylord's other house was owned by James McCrorey, broker. McCrorey let the house to Henry Horn, police constable, in the late 1890s when the NAV had gone down to £20. Horn was tenant still in 1902 when John F. Ogle, chemist, became the new owner. The Ogles, a notable family of chemists, who arrived in Maryborough in the 1850s and had a shop in High Street, the town's commercial centre, purchased the Inkerman Street house as an investment and never lived there. Alfred Verey, bootseller, was the occupying tenant in 1909 and in

Weatherboard Residence Cont.

1919-1920 when Mrs. Agnes Ogle was listed as owner. 6 In 1921, John F. Ogle<sup>3</sup> sold to Reginald Kennedy, mechanic. Kennedy lived in the weatherboard house, which in 1925 had an NAV of £27. 13 In the early 1930s, a new owner, John Duncan, engine driver, was listed. 8 He was owner/occupier still in 1935 of the weatherboard house in part of allotment 13, section 45, then described as 77 Inkerman Street and now 42 Inkerman Street. 14

#### DESCRIPTION:

Style late Victorian. Design standard. Plan rectangular. Single storeyed. Walls timber stud construction, weatherboard clad. Roof hipped with shallow eaves, corrugated iron clad. Features are the cast iron decorated front verandah, symmetrical front elevation, front door and the chimney.

## BIBLIOGRAPHY:

- Maryborough RB 1893 NO.1295 (the southern part of Inkerman Street was known then as Carlyle Street).
- Ibid. 1902 NO.1338 (NAV £20).
- Ibid. 1921-22 No.1350.
- Osborn and DuBourg, Maryborough, pp.77, 86, 114, 169, 248-9,
- Maryborough RB 1897-98 No.1323 (NAV £22).
- 6. Ibid. 1918-20 No.1338; Ibid. 1920 No.1338.
- 7. Ibid. 1921-21 No.1350 (Transfer from Ogle to Kennedy).
- Ibid. 1931-32 No.1461.
- Ibid.1 892-93 No.1244.
- 10. Ibid. 1897-28 No.1294 (Also spelled Gaylaid).
- 11. Ibid. 1898-99 No.1314. 12. Ibis. 1909-10 No.1416 (NAV £25).
- 13. Ibid. 1924-25 No.1379.
- 14. Ibid. 1935-36 No.1658.

# CONSERVATION GUIDELINES:

Regular maintenance as necessary.

Collect roof and ground-water and take well away from the

When repainting, use original/period paint colours and placement.

Erect period/appropriate period front fence.

City of Maryborough Heritage Study

BRICK SHOP AND DWELLING, 47 INKERMAN STREET, MARYBOROUGH.

(CA 1 SECT. 42)

BUILT:

 $1877^{1}$ 

1903-4 ALTERATIONS AND ADDITIONS<sup>2</sup> (EASTERN

END)

EARLY/MID 20TH CENTURY

SHOPFRONT

THEMES ILLUSTRATED BY THIS PLACE:

PRIVATE BUILDING -

**VICTORIAN** 

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE:

ENTIRE BUILDING, ANY OTHER


PRE 1920 STRUCTURES AND

SITE.

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION

CONSERVATION AREA - MARYBOROUGH WEST



Brick Shop and Dwelling Cont.

## CULTURAL SIGNIFICANCE:

This 1877 corner brick shop and dwelling¹ with turn of the century alterations and additions² is one of the oldest in Maryborough and has historical significance. It exemplifies the premises constructed for local businessmen in the 1870s and has particular significance for its associations with William O'Brien, an early Maryborough storekeeper,¹ and, from the turn of the century, with the notable Maffescioni family² of wood merchants, dealers, fruiterers and, most recently, bus proprietors. The modest scale and design of this building typifies the sort of shop building commonly found in most 19th century Victorian towns and cities.

HISTORY:

Original Use:

Shop and dwelling.

Later Use:

Private residence.

Original Owner:

1877-1890s William O'Brien, storekeeper, in 1897 miner, 1898 labourer.

Later Owners:

1900 Marjory Taylor, merchant.<sup>3</sup>

1902- Bernard Maffescioni, wood merchant and dealer.<sup>2</sup>

Mid 1930s Bernard Maffescioni (Junior?), fruiterer.<sup>4</sup>

William O'Brien, storekeeper's brick house and store on the corner of Napier Street and Carlyle Street (the earlier name for the southern part of Inkerman Street) was listed in the Maryborough rate books for the first time in 1877. It was described as a brick house and shop, NAV £25. In 1895, O'Brien's brick shop and residence still had an NAV of £25. In 1896 the NAV decreased to £206 and in 1897 to £16. By this date, O'Brien was described as a miner and the property as a brick house. Later, in 1898, O'Brien was listed as a labourer and the NAV of his Carlyle Street property had fallen to £14. O'Brien seems to have been one of the local businessmen ruined by the 1890s economic depression. Marjorie Taylor, merchant, owned the former brick shop and dwelling in 1900 when its NAV was only £12.

Brick Shop and Dwelling Cont.

Two years later, in 1902, the property was transferred from the executors of the late Marjorie Taylor to Bernard Maffescioni, wood merchant.  $^2$  From this date the building was described simply as a brick, or brick and stone house. Maffescioni, who was listed in the 1903-4 Maryborough rate book as a dealer, may have carried out additions and alterations to the building in the post-1903 period when the NAV rose to £20 and then £30.9 In 1909, described as a brick house, Maffescioni's property was occupied by George L. Bryant, mining manager. 10 Alfred Whitely, agent, became its occupier in 1920 11 and, in 1925, Eric Porter, machinist. 12 By this date the NAV had risen to £40. Frederick Bartlett, labourer, was the occupying tenant in 1931. 13 In the middle 1930s, Bernard Maffescioni, fruiterer, was listed as owner of the brick and stone house in allotment 1 Section 42 at 80 Inkerman Street (now 47 Inkerman Street).<sup>4</sup> This Bernard Maffescioni was the son of Bernard Maffescioni, wood merchant and dealer.

#### DESCRIPTION:

Style mid Victorian. Design standard. Plan rectangular. Single storeyed. Walls face brick.

Roof hipped and corrugated iron clad, parapet to both street

Features are the parapet, door and window openings, shopfront and the wall plate for the demolished post-supported verandah.

## BIBLIOGRAPHY:

- Maryborough RB 1877 No.256 (Property listed in allotment 1 Section 42).
- Ibid. 1902-3 No.1303.
- Ibid. 1900-1901 No.1270. 3.
- Ibid. 1936-37 No.1620.
- Ibid. 1895-96 No.1296. 5.
- Ibid. 1896-97 No.1296. 6.
- Ibid. 1897-98 No.1288. 7.
- Ibid. 1898-99 No.1279.
- Ibid. 1903-4 No.1316; Ibid. 1905-6 No.1369.
- 10. Ibid. 1909-10 No.1381.
- 11. Ibid. 1920 No.1304. 12. Ibid. 1925-26 No.1348.
- 12. Ibid. 1931-32 No.1424.

- 4 -

Brick Shop and Dwelling Cont.

# CONSERVATION GUIDELINES:

Chemically remove paint from face brick walls to return to most probable original appearance, checking for any difference in bricks used between the two sections and any rough alterations to the brickwork.

Remove cantilevered verandah.

Repaint joinery in original/period paint colours and placement.

Regular maintenance as necessary.

# CREAM FACE BRICK HOUSE,

49 INKERMAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s C.1950 □ 1900s or 1910s □ 1920s-1930s □ 1940s ■ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and □ Gold Discoveries □ First Survey and Original □ Local Government and Growth of the Town □ Transport □ (Mining and Other) ■ Socio-economic □ Public and □ Education □ Health □ Mix in the Town □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Edwardian □ Inter-war Housing □ Inter-war Housing
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE    Entire Place (Heritage and Site)   Including Other Sites   Other  RECOMMENDATION   Should be conserved - C   Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect □ Designer □ Builder □ Manufacturer of Components □ Tradesman □ Garden Design □ Garden Planting □ Garden Maintenance and Development □ Associations with Person/Group/Body □ Botanical Significance □ Construction Significance □ Engineering Significance □ Historic Significance □ Horticultural Significance □ Landscape Significance □ Manufacturing Significance □ Streetscape Significance □ Townscape Significance □ In Comparison With Other Places in Maryborough □ Typical ■ Unusual □ Unusual Design, Features □ Good Quality Design, Features □ Typical Design, Features
DESCRIPTION  Place Contains  Main Building  Outbuilding/s of Significance  Individual Planting of Significance or Significance  Interest as Structures  Part of Garden OR □ Individually Structures  Tother  Other  Other  Other  Other  Other  Other  Other  Discription  Garden of Significance or Interest  Building of Significance Buildings of No Significance Significance U Visible  Other

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE 1950S
DESIGN  ■ Standard □ One-off □ Unique □ Flat Fronted □ Double Fronted  ■ More Than Two Fronts □ Other
PLAN  ☐ Rectangular   Other
STOREYS  Single
☐ All of the One Basic Material ☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
Brick - Face Brick - Rendered Brick - Painted Later? Corrugated Iron Timber Stud Framed/ Vernacular Timber Stud/Split or Sawn Paling Clad Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction  Roof (Main Roof (1), Additions (2)-) Pitched Gabled Lean-to Timber Shingles Shingles Rarrow Eaves Canvas
Wide Eaves □ Slate Cladding ■ Terracotta Tile □ Flat Metal Sheet □ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium ☐ Exterior Doors ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass
☐ Timber ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use

	FACE BRICK HOUSE,
	53 INKERMAN STREET, MARYBOROUGH.
	BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s 1935 □ 1900s or 1910s ■ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
	THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries Town Plan □ Transport (Mining and Other) □ Socio-economic □ Public and □ Private Building □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Edwardian □ Inter-war Housing □ Post World War Two
)	DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  ☐ Entire Place (Heritage and Site) ☐ Heritage Item Alone  ☐ Other  RECOMMENDATION  Should be conserved - C ☐ Conservation Area
	CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect □ Designer □ Builder □ Manufacturer of Components □ Tradesman □ Garden Design □ Garden Planting □ Garden Maintenance and Development □ Associations with Person/Group/Body □ Botanical Significance □ Construction Significance □ Engineering Significance □ Historic Significance □ Horticultural Significance □ Landscape Significance □ Manufacturing Significance ■ Streetscape Significance □ Townscape Significance ■ In Comparison With Other Places in Maryborough □ Typical □ Unusual ■ Unusual Design, Features □ Good Quality Design, Features □ Typical Design, Features
	DESCRIPTION  Place Contains

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE 1930S
DESIGN  ■ Standard □ One-off □ Unique □ Flat Fronted ■ Double Fronted □ More Than Two Fronts □ Other
PLAN Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS □ All of the One Basic Material ■ Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
Brick - Face Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
☐ Flat ☐ No Eaves ☐ Narrow Eaves ☐ Canvas ☐ Wide Eaves ☐ Slate Cladding ☐ Terracotta Tile ☐ Flat Metal Sheet ☐ Corrugated Iron ☐ Patent Metal Roofing ☐ Timber Shingles ☐ Metal Deck ☐ Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ■ Intact
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Threatened by Subdivision □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

FOUTE

FORMER WESLEYAN METHODIST JUBILEE CHURCH (FIFTH AND LAST CHURCH), S.W. CNR. CLARENDON STREET, INKERMAN STREET, MARYBOROUGH.

63 Inkerman Street

SEE ALSO 1860 FOURTH WESLEYAN METHODIST CHURCH ON THE WEST SIDE.

BUILT:

 $1886^{1}$ 

1910 OR 1911 PIPE ORGAN INSTALLED<sup>3</sup>

1958 ORGAN ENLARGED<sup>3</sup>

1981 ORGAN MOVED TO THE UNITING (FORMER PRESBYTERIAN)

CHURCH<sup>2</sup>

THEMES ILLUSTRATED BY THIS PLACE:

RELIGION

PRIVATE BUILDING -

VICTORIAN

DEGREE OF SIGNIFICANCE:

· REGIONAL SIGNIFICANCE


EXTENT OF SIGNIFICANCE:

ENTIRE BUILDING AND SITE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION

CONSERVATION AREA - MARYBOROUGH WEST



Former Wesleyan Methodist Jubilee Church Cont.

## CULTURAL SIGNIFICANCE:

The youngest of Maryborough's 19th century churches and architecturally the most innovative for its time, the fifth and last Wesleyan Church illustrates the strength of the town's Methodists at that time, relative to the other churches in the town, and the use of up-to-date detailing for the nave part of what was intended to be a larger church, probably with transepts. The main elevation of Maryborough's only polychromatic brick church has a projecting central section and angled corner porches to each side, both very unusual if not unique details in a Victoria-wide context. The rose window is the only one in Maryborough. The elaborate mouldings above the front doors are finely detailed and rare anywhere in the State. In the context of 1880s churches in Victoria, this building is a good example of a duochromatic brick church with some rare if not unique details. This church is also a significant streetscape element. The fourth Wesleyan Church of 1860 is adjacent and the long period of use of the site by the Wesleyans, from circa 1860 until probably circa 1977, enhances the significance of both buildings and their now separated sites. This church contained Maryborough's most substantial pipe organ, built in 1910/1911 by Frederick Taylor4, and donated by prominent mining entrepreneur Ivor Davies, until it was moved to the Uniting Church in 1981.<sup>2</sup> The 1867 Church of Christ is one the opposite side of Inkerman Street.

HISTORY:

Original Use:

Wesleyan Methodist church.

Present Use:

Disused - privately non-church owned.

Original Owner:

1886-1981?<sup>2</sup> Wesleyan

Methodist Church

Later Owners:

1977? Uniting Church


Contractor:

1886 William Phelan<sup>2</sup>

Cost:


 $£1,675^2$ 


The Wesleyan services were first held in Maryborough in 1854 and in 1855 the first minister, Rev. Martin Dyson, was appointed by the Castlemaine minister.<sup>3</sup> The first two churches were weatherboard buildings.<sup>3</sup> The third church of 1860 survives on the west side of the fourth church.



- 44.2

200





Former Wesleyan Methodist Jubilee Church Cont.

### DESCRIPTION:

Style 1880s polychromatic Gothic.

Design conventional if large nave with unusual front design and detailing.

Plan rectangular with projecting front section and low angled porches to each corner. Rear weatherboard chancel/vestry and with two entries, 4 bays long.

Single storeyed.

Walls solid face brick.

Roof gabled with no eaves, corrugated iron clad. Porches

apparently also have a hipped roof.

Features are the projecting front section with its stucco rose window, gable vent, blind triple arch and foliated window finial, the angled porches with their decorated gables over the doors, main gabled with its oculus louvre vent, red and cream diagonal tiles and cross and the twin windows to each bay of the nave.

### BIBLIOGRAPHY:

1. Memorial stone laid 23 June 1886 by Mr. Thomas Lancaster.

2. Betty Osborn and Trenear Du Bourg, <u>Maryborough</u>, City of Maryborough, 1985, p.273.

3. Ibid., pp.136-138.

4. E.N. Matthews, <u>Colonial Organs and Organbuilders</u>, Melbourne University Press, Carlton, 1969, p.174.

5. The Rev. C. Irving Benson, <u>A Century of Victorian Methodism</u>, Spectator Publishing Co., Melbourne, 1935, p.448.

# CONSERVATION GUIDELINES:


Regular maintenance as required.


Ensure spouting is regularly cleared and all roof and ground-water is carried well away from the building. Monitor tree roots to ensure that they do not cause any

structural cracking.

If the front two trees were moved/cut down then the building could be seen from the street and its beauty appreciated.

Chemically remove white paint from the rendered areas, or paint in an appropriate colour, such as sandstone. Also remove paint from stone plinth. When repainting continue to use original/period paint colours and paint rear weatherboard section in the above colours.





Fourth Wesleyan Methodist Church Cont.

# CULTURAL SIGNIFICANCE:

Maryborough's oldest surviving church building, this structure illustrates the strength of the Wesleyan Methodist Church in Maryborough in the early decades of the town's history when the other denominations were occupying tents/slab buildings or still to arrive. The spire and tower is an unusual design and well detailed. Maryborough has just two 19th century spires, this building and the later Catholic church (1872), which has otherwise been destroyed. The original form of this building has been distorted by the additions at each end and the unsympathetic recent windows. However, both the historic and streetscape importance of the building remain untouched.

HISTORY:

Original Use: Methodist Church

Present Use: State School use.

Contractor: 1860 Thomas Taggart<sup>1</sup>

Cost: 1860 £218-15-91

1880 £300<sup>2</sup>

This church was the fourth Wesleyan Church, its predecessors being a tent, followed by two successive wooden chapels.¹ The first Methodist services were held in Maryborough in 1854 by Thomas Henry Evans, Mr. Rhodes and Mr. Morgan.¹ In April 1855 Maryborough's and the Wesleyan's first minister, Rev. Martin Dyson, was appointed by the Castlemaine minister.¹ This first brick church served the congregation for 27 years, until the much larger adjacent fourth church was constructed in 1887.¹ The old church, then known as Wesley Hall, was added to in 1880.²

# DESCRIPTION:

Style mid Victorian Gothic.

Design main body standard, tower and spire uncommon.

Plan rectangular with rectangular additions on the south-east corner and west end.

Single storeyed.

Walls solid face brick.

Roof gabled with no eaves, corrugated iron clad.

Features are the tower and spire, added sections and the original east windows.

FOURTH WESLEYAN METHODIST CHURCH, S.E. CNR. WELLINGTON STREET, INKERMAN STREET, MARYBOROUGH.

65 Inkerman st

SEE ALSO FIFTH WESLEYAN METHODIST CHURCH ON THE EAST SIDE.

BUILT:

18601 - OPENED CHRISTMAS DAY4

1880 ADDITION<sup>2</sup>

THEMES ILLUSTRATED BY THIS PLACE:

PRIVATE BUILDING -

VICTORIAN

LOCAL GOVERNMENT AND GROWTH OF THE TOWN

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE:

ENTIRE BUILDING AND SITE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION

CONSERVATION AREA - MARYBOROUGH WEST

Fourth Wesleyan Methodist Church Cont.

# BIBLIOGRAPHY:


- 1. Betty Osborn and Trenear Du Bourg, Maryborough, City of Maryborough, 1985, p.136-138.
- 2. Ibid., p.293.

3. Ibid., p.273.

4. The Rev. C. Irving Benson, <u>A Century of Victorian Methodism</u>, Spectator Publishing Co., Melbourne, 1935, p.448.

# CONSERVATION GUIDELINES:

Regular maintenance as required.
Reconstruction of original window openings and glazing.
When repainting use original/period paint colours and placement.
Ensure that all roof and ground-water is taken well away from the building.



City of Maryborough Heritage Study

# WEATHERBOARD HOUSE,

□ Other

75 INKERMAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries □ First Survey and Original □ Local Government and Growth of the Town □ Transport □ Health □ Socio-economic □ Public and □ Private Building □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  Entire Place (Heritage and Site)  Heritage Item Alone    Dest World War Two
RECOMMENDATION Should be conserved - C  Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  ☐ Architectural Significance ☐ Architect ☐ Designer ☐ Builder ☐ Manufacturer of Components ☐ Tradesman ☐ Garden Design ☐ Garden Planting ☐ Garden Maintenance and Development ☐ Associations with Person/Group/Body
□ Botanical Significance       □ Construction Significance       □ Engineering Significance         □ Historic Significance       □ Horticultural Significance       □ Landscape Significance         □ Manufacturing Significance       ■ Streetscape Significance       □ Townscape Significance         ■ In Comparison With Other Places in Maryborough       □ Typical       □ Unusual       □ Unusual Design, Features       □ Good Quality Design, Features       ■ Typical Design, Features
DESCRIPTION  Place Contains   Main Building □ Garden of Significance or Interest □ More than One Main  Outbuilding/s of □ Individual Planting of Significance or Significance □ Interest as □ Building of Significance  Garden or Other □ Part of Garden OR □ Individually Structures □ Front Fence OR □ Visible

 $\square$  Other Fences of Significance or Interest


HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single Single and Part Cellar Single and Full Basement More Than Two Storeys  Two Storeyed Two Storeyed With Part Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials  Original (1) and Later () Section Materials
Walls   □ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed/   ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction □ Other   Roof (Main Roof (1), Additions (2)-) □ Gabled □ Lean-to □ Timber Shingles   □ Flat □ No Eaves □ Narrow Eaves □ Canvas   □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet   ■ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck   Tiles
Windows  Original Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Secondary Elements ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use

□ Other

# FULLERS BAKERY BUILDINGS,

79 INKERMAN STREET, MARYBOROUGH.
BUILT       □       1850s       □       1860s       □       1870s       ■       1880s or 1890s         ■       1900s or 1910s       ■       1920s-1930s       □       1940s       □       1950s         □       1960s       □       1970s       □       1980s       □       1990s
THEMES IDENTIFIED BY THIS PLACE    Exploration and
EXTENT OF SIGNIFICANCE Entire Place (Heritage and Site) Including Other Sites  Heritage Item Alone Other  RECOMMENDATION Should be conserved - C  Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect Designer Builder Manufacturer of Components
□ Tradesman       □ Garden Design       □ Garden Planting       □ Garden Maintenance and Development         □ Associations with Person/Group/Body       □ Botanical Significance       □ Construction Significance       □ Engineering Significance         ■ Historic Significance       □ Horticultural Significance       □ Landscape Significance         □ Manufacturing Significance       ■ Streetscape Significance       □ Townscape Significance         ■ In Comparison With Other Places in Maryborough       □ Typical       ■ Unusual       □ Unusual Design, Features       □ Good Quality Design, Features       □ Typical Design, Features
DESCRIPTION  Place Contains  Main Building  Outbuilding/s of Significance or Interest Significance  Garden or Other Structures  DESCRIPTION  Part of Significance or Interest Individual Planting of Significance or Building of Significance Buildings of No Significance Significance Significance Front Fence OR  Visible

☐ Other Fences of Significance or Interest





HISTORY KNOWN  ☐ Yes No		79 Interman
USE ☐ Present Use Same as Original	☐ Different Original Use ☐ Know	vn Later Use or Interest
STYLE VICTORIA	N/EARLY/MID 20TH CENTURY	,
DESIGN  ■ Standard ■ One-off □ More Than Two Fronts □		Pouble Fronted
PLAN ■ Rectangular □ Other		
	nd Part Cellar ☐ Single and Full Bas breyed With Part ☐ Two Storeyed with Basement Cellar	
☐ All of the One Basic Material  More Than Two Basic Materials  Walls	☐ Two Basic Materials ☐ Original (1) and Later () Section	Materials
Brick - Face  □ Brick - Probably Painted □ St  □ Vernacular Timber Stud/Split or  □ Weatherboard Clad Timber Stud  Roof (Main Roof (1), Additions (2)-)  □ Pitched  □ Flat  □ No Ear  ■ Wide Eaves  □ Slate Corrugated Iron  □ Patent	Sawn Paling Clad Framed/Metal Stud Framed Construction  d	Later? Corrugated Iron Timber Stud Framed/ Metal Framed Other  Timber Shingles Canvas Flat Metal Sheet Metal Deck
Windows  Original Timber  Steel Framed  Exterior Doors Original Timber  Tiles  Some Later  Steel Framed  Timber  Timber  Timber  Timber  Timber	☐ All Later ☐ Leadlight, Sta	
SIGNIFICANT FEATURES		
☐ Secondary Elements ☐		the Significance from the Significance
CONDITION  ☐ Excellent ☐ Poor ☐ Remains Only	■ Fair □ Substantially Decayed	
☐ In-use ☐ I	UENCE THE PLACE'S SURVIVAL  Disused	☐ Threatened by Adjacent Use nance ☐ Threatened by Subdivision

City of Maryborough Heritage Study

FACE BRICK HOUSE, 86 INKERMAN STREET, MARYBOROUGH.

BUILT: 1870S/1880S/1890S/1900S

1900S CAST IRON FRIEZE

(AND VERANDAH)

THEMES ILLUSTRATED BY THIS PLACE: PRIVATE BUILDING -

VICTORIAN


DEGREE OF SIGNIFICANCE: LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE: ENTIRE BUILDING AND SITE,

NOTING THAT THERE ARE EXTENSIVE REAR ADDITIONS.

RECOMMENDATIONS: LOCAL PLANNING PROTECTION

CONSERVATION AREA - MARYBOROUGH WEST



Face Brick House Cont.

### CULTURAL SIGNIFICANCE:

One of the very small number of 19th century brick houses (as distinct from residences) in Maryborough, this building is also the only one in this part of the City. Though screened by planting, this house has a role in the streetscape and begins a short line of 19th/early 20th century dwellings of streetscape importance that ends at the former gaol buildings on the top of the rise. The slate roof cladding is (now) very rare for dwellings in Maryborough and illustrates the home of a better-off Maryborough resident during a period of growth. The traditional lack of affluence in the Municipality has meant that what would have been a standard type of dwelling in Ballarat or Melbourne during the same period becomes an uncommon one in Maryborough.

### HISTORY:

Original and Continuing Use:

Dwelling

# DESCRIPTION:

Style mid Victorian.

Design standard.

Plan rectangular.

Single storeyed.

Walls solid face brick.

Roof hipped with shallow eaves, slate clad.

Features are the hipped slate roof, symmetrical front facade, the cast iron frieze, decorated timber front, verandah and the chimneys, the top of the western one dating from the 1930s or later.

# CONSERVATION GUIDELINES:

Regular maintenance as necessary.

Collect all roof and ground-water and take well away from the building. Buildings in this situation often suffer from rising damp on the up-hill wall, unless in-ground drainage is supplied.

# WEATHERBOARD HOUSE,

90 INKERMAN STREET, MARYBOROUGH.			
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s 1901? ■ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s			
THEMES IDENTIFIED BY THIS PLACE  Exploration and Pastoral Settlement Coal Industries Town Plan  Transport (Mining and Other) Socio-economic Public and Private Planting  Religion Notable Men Post World War Two			
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  □ Heritage Item Alone  RECOMMENDATION  Should be conserved - C  □ Conservation Area			
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Garden Designer  Garden Planting  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Historic Significance  Horticultural Significance  Manufacturing Significance  Streetscape Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual  Unusual Design, Features			
DESCRIPTION  Place Contains			

☐ Yes No				
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest				
STYLE EDWARDIAN?				
DESIGN  ■ Standard □ One-off □ Unique □ Flat Fronted ■ Double Fronted □ More Than Two Fronts □ Other				
PLAN  Rectangular  Other				
STOREYS  Single Single and Part Cellar Single and Full Basement Two Storeys Two Storeyed Two Storeyed With Part Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials More Than Two Basic Materials Original (1) and Later () Section Materials				
Walls   □ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed   ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction □ Other   Roof (Main Roof (1), Additions (2)-) □ Pitched ■ Gabled ■ Lean-to □ Timber Shingles   □ Flat □ No Eaves ■ Narrow Eaves □ Canvas   □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet   ■ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck				
Windows   Image: Control of the properties of the prop				
SIGNIFICANT FEATURES				
INTACTNESS  Intact □ Additions □ Alterations □ Secondary Elements □ Part of the Significance □ Part of the Significance □ Detract from the Significance □ Detract from the Significance				
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only				
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use				

	RMAN STRE	ΕI,	
MARYBO	ROUGH.		
BUILT 🗆	1850s		1860s
	1900s or 1910s		1920s-1930s
	1960s		1970s

Education

Religion

Exploration and ☐ Gold Discoveries ☐ First Survey and Original Pastoral Settlement ☐ Local Industries Transport

Town Plan (Mining and Other) ☐ Socio-economic

□ 1870s

□ 1940s

□ 1980s

☐ Health □ Notable Men and Women

Mix in the Town ☐ Sport and Recreation

☐ Public and Private Planting

☐ Local Government and Growth of the Town

☐ Public and

Private Building

6 Victorian **Edwardian** 

Inter-war Housing Post World War Two

DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE Entire Place (Heritage and Site) ☐ Heritage Item Alone

☐ Including Other Sites □ Other


1880s or 1890s

1950s

1990s

RECOMMENDATION Should be conserved - C

Conservation Area



# **CULTURAL SIGNIFICANCE**

### **Basis of Significance**

Architectural	Significance

☐ Architect □ Designer ☐ Tradesman ☐Garden Design

☐ Builder ☐ Garden Planting Manufacturer of Components

☐ Garden Maintenance and Development

☐ Associations with Person/Group/Body

☐ Botanical Significance ☐ Historic Significance

☐ Construction Significance ☐ Horticultural Significance

Engineering Significance Landscape Signficance

Manufacturing Significance Streetscape Significance

Townscape Significance

In Comparison With Other Places in Maryborough

🗆 Typical 🗆 Unusual 🗖 Unusual Design, Features 🗆 Good Quality Design, Features 🔳 Typical Design, Features

### DESCRIPTION

#### **Place Contains**

Main Building

Outbuilding/s of Significance

Garden or Other Structures

□ Other

☐ Garden of Significance or Interest ☐ Individual Planting of Significance or

Interest as

☐ Part of Garden OR ☐ Individually

☐ Front Fence OR ☐ Other Fences of Significance or Interest More than One Main Building of Significance

Buildings of No Significance


☐ Visible

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other  PLAN
Rectangular   Other
STOREYS  Single Single Single and Part Cellar Single and Full Basement Two Storeyed With Part Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
□ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use Disused Abandoned Threatened by Adjacent Use Unsympathetic Use Sympathetic Use Basic Maintenance Cosmetic Maintenance Required Threatened by Redevelopment Required  Threatened by Subdivision

Ba	sis of Significance
	Architectural Significance
	☐ Architect ☐ Designer ☐ Builder ☐ Manufacturer of Components
	☐ Tradesman ☐ Garden Design ☐ Garden Planting ☐ Garden Maintenance and Development
	Botanical Significance
	Manufacturing Significance □ Streetscape Significance □ Townscape Significance
	■ Typical ■ Unusual □ Unusual Design, Features □ Good Quality Design, Features □ Typical Design, Features
DE	ESCRIPTION

e	ontains			
1	Main Building	Garden of Significance or Interest		More than One Main
	Outbuilding/s of	Individual Planting of Significance or		Building of Significance
	Significance	Interest as		Buildings of No
	Garden or Other	☐ Part of Garden OR ☐ Individually		Significance
	Structures	Front Fence OR		□ Visible
	Other	☐ Other Fences of Significance or Interes	t	

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials
□ More Than Two Basic Materials □ Original (1) and Later () Section Materials   Walls □ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed   ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction □ Other   Roof (Main Roof (1), Additions (2)-) □ Lean-to □ Timber Shingles   □ Flat □ No Eaves ■ Narrow Eaves □ Canvas
□ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet   ■ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck   Tiles    Windows  Windows  Original  □ Some Later □ All Later □ Leadlight, Stained Glass  ■ Timber □ Some Later □ All Later □ Leadlight, Stained Glass ■ Timber □ Timber and Glass □ Metal □ Leadlight, Stained Glass ■ Timber □ Timber and Glass □ Metal □ Leadlight, Stained Glass ■ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use Disused Abandoned Threatened by Adjacent Use Unsympathetic Use Sympathetic Use Basic Maintenance Cosmetic Maintenance Required Threatened by Redevelopment Required



City of Maryborough Heritage Study

FORMER GAOL OFFICE AND RESIDENCE BUILDINGS, 94 AND 96 INKERMAN STREET, MARYBOROUGH.

BUILT:

1861

C.1930 FACADE ROUGHCAST RENDERED ADDITIONS AND ALTERATIONS DURING CONVERSION INTO FLATS

THEMES ILLUSTRATED BY THIS PLACE:

GOLD DISCOVERIES

LOCAL GOVERNMENT AND THE GROWTH OF THE TOWN

PUBLIC BUILDING - VICTORIAN

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE:

ALL OF BOTH BUILDINGS AND

ENTIRE SITE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION

CONSERVATION AREA: BARKLY STREET-INKERMAN STREET



- 2 -

Former Gaol Office Cont.

### CULTURAL SIGNIFICANCE:

The only remains of the Maryborough Gaol on their original site, these two landmark buildings have historic significance, are important streetscape elements and are important survivors from the first decade of gold mining, which saw the settlement appear from nothing and be sufficiently important to justify the construction of a full-size gaol. Throughout its life the Gaol dominated western Maryborough from its site on the top of the rise. The City has virtually no non-commercial two storeyed buildings, which gives these two buildings added prominence in their surroundings. Victoria has a small number of these standard design gaols, the nearest examples being at Bendigo, Ballarat and Ararat.

HISTORY:

Original Use:

Maryborough Gaol

Present Use:

Flats

Original Owner:

Colonial Government of

Victoria

Later Owners:

Architect:

Public Works Department of

Victoria

# DESCRIPTION:

Style late Georgian/early Italianate. Design standard Public Works Department one.

Plan rectangular with projecting rear section.

Two storeyed.

Walls solid bluestone/face brick, now roughcast rendered.

Roof hipped with eaves, slate clad.

Features are the roundheaded ground floor front windows with their curved glazing bars, multi-pane windows, rusticated bluestone quoins, stringcourse, eaves, slate roof and the rusticated bluestone plinth.

- 3 -

Former Gaol Office Cont.

# BIBLIOGRAPHY:

1. Public Works Department of Victoria original drawings (in Plan Room, Department of Planning and Housing).


2. Betty Osborn and Trenear DuBourg, Maryborough, City of Maryborough, 1985.


### CONSERVATION GUIDELINES:

Regular maintenance as necessary.

Collect all roof and ground-water and take well away from the building.


Carefully remove roughcast render from the wall surfaces. When repainting use original/period colours and placement. Treat the street frontages and the land between the two buildings so that they are linked, rather than treated as two separate properties.







GATES AND SHED.

FRONT ENTRANCE CATE








INTERNAL GATES




PLAN FROM PLAN ROOM, DEPARTMENT OF PLANNING AND DEVELOPMENT (PREVIOUSLY PUBLIC WORKS DEPARTMENT)










MARYBOROUGH GAOL

BASEMENT FLAN








SCALE 20 FEET TO AN INCH Standed by Som.

# MARYBOROUGH CAOL

FIRST FLOOR PLAN






PUBLIC WORKS OFFICE WELBOOK
Orasin by (21)

Scale 20 FEET TO AN INON Grinked by Star




MARY BOROUGH GAOL

GROUND PLAN





SCALE 20 FEET TO AN INCH Finded by Alta. CG 2495

1.7




GAOLER'S AND WARDERS' QUARTERS.





Public Wirks (ffice Melbourne 267/60 PP






Back Elevation & Section through Killiens


**CG** 2504

Scale Eight feel to an inch.

PLAN FROM PLAN ROOM, DEPARTMENT OF PLANNING AND DEVELOPMENT (PREVIOUSLY PUBLIC WORKS DEPARTMENT) GAOLER'S AND WARDERS' QUARTERS.




PLAN FROM PLAN ROOM,
DEPARTMENT OF PLANNING AND
DEVELOPMENT (PREVIOUSLY
PUBLIC WORKS DEPARTMENT)



PLAN FROM PLAN ROOM,
DEPARTMENT OF PLANNING AND
DEVELOPMENT (PREVIOUSLY
PUBLIC WORKS DEPARTMENT)

PLAN or ROOF




SOUTH ELEVATION OF N. W. WITTE AND CENTRAL LAN


Public Works Chiles


25 Thomas 30 4 3rd 59 9.19


PLAN FROM PLAN ROOM,
DEPARTMENT OF PLANNING AND
DEVELOPMENT (PREVIOUSLY
PUBLIC WORKS DEPARTMENT)

1.12









### WEATHERBOARD COTTAGE,

99 INKERMAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries □ Town Plan □ Transport □ Local Industries □ Socio-economic □ Public and □ Private Building □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing □ Post World War Two
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  Entire Place (Heritage and Site)  Heritage Item Alone  Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Designer  Garden Design  Garden Planting  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Historic Significance  Horticultural Significance  Horticultural Significance  Manufacturing Significance  Streetscape Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual  Unusual Design, Features
DESCRIPTION  Place Contains   Main Building  Outbuilding/s of Significance  Individual Planting of Significance or Building of Significance  Interest as  Garden or Other Structures  □ Other Fences of Significance or Interest  Typical Design, Features  More than One Main Building of Significance Building of Significance Significance  Significance  U Visible  Under Fences of Significance or Interest

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials  More Than Two Basic Materials □ Original (1) and Later () Section Materials
Walls         □ Brick - Face       □ Brick - Rendered       □ Brick - Painted Later?       □ Corrugated Iron         □ Brick - Probably Painted       □ Stone       Timber Stud Framed/         □ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed         ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       □ Other         Roof (Main Roof (1), Additions (2)-)       □ Pitched       □ Gabled       □ Lean-to       □ Timber Shingles         □ Flat       No Eaves       □ No Eaves       □ Canvas         □ Wide Eaves       □ Slate Cladding       □ Terracotta Tile       □ Flat Metal Sheet         □ Corrugated Iron       □ Patent Metal Roofing       □ Timber Shingles       □ Metal Deck         □ Tiles
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Threatened by Subdivision □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

# BRICK RESIDENCE,

100	INKE	ERMAN	STR	EEI	9.
		***********			·····
MAR	YBOR	OUGH.			

BUILT	1850s	1860s	1870s	1880s or 1890s	1949
	1900s or 1910s	1920s-1930s	1940s	1950s	
	1960s	1970s	1980s	1990s	

#### THEMES IDENTIFIED BY THIS PLACE

Exploration and	Gold Discoveries		First Survey and Original	Lox	cal Government
Pastoral Settlement	Local Industries		Town Plan	and	d Growth of the Town
Transport	(Mining and Othe	r)	Socio-economic	Pul	olic and
Education	Health		Mix in the Town		Private Building
Religion	Notable Men		Sport and Recreation		Victorian
	and Women		Public and Private Planting		Edwardian
					Inter-war Housing
					Post World War Two


#### DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE Entire Place (Heritage and Site) 

Including Other Sites ☐ Heritage Item Alone ☐ Other

RECOMMENDATION Should be conserved - C

Conservation Area



#### **CULTURAL SIGNIFICANCE**

### Basis of Significance

Du	is of Digititeance				
	Architectural Significance	;			
	☐ Architect	□Designer	☐ Builder		Manufacturer of Components
	☐ Tradesman	☐Garden Design	☐ Garden Planting	, 0	Garden Maintenance and Development
	Associations with Person/	Group/Body			
	Botanical Significance	☐ Construc	ction Significance		Engineering Significance
	Historic Significance	☐ Horticult	tural Significance		Landscape Signficance
	Manufacturing Significant	ce Streetsca	ape Significance		Townscape Significance
	In Comparison With Othe		orough		
		Unusual Design		uality	Design, Features   Typical Design, Features
DE	SCRIPTION				

#### Plac

ce C	Contains			
	Main Building	Garden of Significance or Interest		More than One Main
	Outbuilding/s of	Individual Planting of Significance or		Building of Significance
	Significance	Interest as		Buildings of No
	Garden or Other	☐ Part of Garden OR ☐ Individually		Significance
	Structures	Front Fence OR		☐ Visible
	Other	☐ Other Fences of Significance or Intere	st	

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE 1940S
DESIGN  ☐ Standard ☐ One-off ☐ Unique ☐ Flat Fronted ☐ Double Fronted  ☐ More Than Two Fronts ☐ Other
PLAN  ☐ Rectangular   Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS □ All of the One Basic Material ■ Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials  Walls
Brick - Face Brick - Rendered Brick - Painted Later?  Brick - Probably Painted Stone Vernacular Timber Stud/Split or Sawn Paling Clad Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction  Roof (Main Roof (1), Additions (2)-) Pitched Gabled  Brick - Painted Later? Corrugated Iron Timber Stud Framed/ Metal Framed Other
Flat
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  ☐ Exterior Doors ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass
☐ Timber ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required □ Required

Adobe/Pise Cottage Cont.

#### CULTURAL SIGNIFICANCE:

One of probably just three dwellings constructed out of earth in Maryborough, this building also exemplifies the modest cottages lived in by many past residents during the 19th and early 20th centuries and has historic significance for its early use by goal turnkeys. The gaol was on the other side of Inkerman Street. Most of this type of cottage have now disappeared. Of the three earth dwellings, this one is the simplest and contrasts with the pre 1920 houses around it. A third owner from 1869 to 1896 was Edward Harkness, builder and timber merchant, Maryborough councillor and mayor in 1868-69. During his ownership of the property Harkness' tenants included Thomas Savage, warder, in the 1890s.

#### HISTORY:

Original and Later Use:

Private Residence

Original Owner:

Matthew Mayer, turnkey.<sup>1</sup>

Later Owners:

Arthur Meadway, turnkey.<sup>2</sup>

Edward Harkness, builder and timber merchant.<sup>3</sup>

S. Ead<sup>6</sup>

Robert Passalick, labourer.

Following the opening of Maryborough gaol in 1861, a number of people associated with its administration occupied cottages in Inkerman Street on its west side opposite the gaol which stretched from Barkly to Goldsmith Street. In 1865 Timothy Gaynor, turnkey, owned and occupied a slab and iron dwelling, NAV £8, in Inkerman Street. It stood near the tent of Matthew Mayer, miner. The following year, Mayer occupied a clay house, NAV £10, in Inkerman Street, which stood between the wood dwelling of Thomas Kean, turnkey, NAV £8 and Thomas Gaynor, turnkey's wooden building, also NAV £8. In 1867, Mayer's house was listed as a mud house. Another turnkey, Arthur Meadway, owned and occupied this building in 1868 when it was described as a brick house, NAV £14.

ADOBE/PISE COTTAGE, S.W. CNR. GOLDSMITH STREET, 101 INKERMAN STREET, MARYBOROUGH.

(C.A. 1A SECT. 39)

BUILT:

1866?1

THEMES ILLUSTRATED BY THIS PLACE:

PRIVATE BUILDING -

VICTORIAN

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE


EXTENT OF SIGNIFICANCE:

ENTIRE BUILDING AND SITE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION

CONSERVATION AREA: BARKLY STREET-INKERMAN STREET



- 3 -

Adobe/Pise Cottage Cont.

From 1869 until 1896 the brick house in allotment 1A Section 39 was owned by Edward Harkness, builder and timber merchant. Born in 1820 in a Cumberland village, Harkness became a wheelwright and carpenter and at 24 went to Liverpool to work at his trade.

In 1853, Harkness left for the Australian colonies, working at first at Collingwood before leaving for the goldfields. He settled in Maryborough and became the owner of a shop which sold timber. In 1857 his carpenter's shop and timber yard stood on the east side of High Street. Harkness was associated with the construction of a number of important Maryborough buildings including a new wing for the hospital (1867-68) and the London Chartered Bank (1870). He took a keen interest in local affairs becoming a councillor in the 1860s and mayor in 1868-69. During his 42 years in Maryborough, Harkness was associated with the hospital, the educational Board of Advice, the Gas Company, Congregational Church, the Protestant Alliance Friendly Society and the Orange Lodge. He was also a trustee of the Savings Bank. When his estate was wound up following his death in July 1896, his "substantially built two-storey brick shop" had to be let.<sup>3</sup>

Among Harkness' tenants in the 1890s was Thomas Savage, a warder. There may have been a connection between the occupancy of the Inkerman Street house and the employment of prisoners during the 1870s and later as a cheap labour force to construct projects within Maryborough township. These public works included the construction of the road to the town cemetery and the excavation of Lake Victoria. The Council provided tools and paid for guards to watch the prisoners during working hours as they carried out Borough works.

The Inkerman Street house was listed in the 1890s as a brick and wood house and then a brick house, NAV £14. A new owner, S. Ead, was rated at the turn of the century when the building was occupied by Thomas Slater, miner. Between 1906 and the 1930s it was owned by Robert Passolick, labourer, and was described as a brick house. NAV £10.

There may have been a connection between the occupancy of the Inkerman Street house and the employment of prisoners during the 1870s and later as a cheap labour force to construct projects within the Maryborough township. These public works included the construction of the road to the town cemetery and the excavation of Lake Victoria. The Council provided tools and paid for guards to watch the prisoners during working house as they carried out Borough works.

Adobe/Pise Cottage Cont.

#### DESCRIPTION:

Style simple Victorian.

Design standard.

Plan rectangular front block with two rooms and later rear line perpendicular to it.

Single storeyed.

Walls; front section adobe (mud brick or pise (rammed earth); rear section same?

Roof; front section gabled with no eaves; rear section hipped with no eaves. Both sections corrugated iron clad.

Features are the modest building porch, symmetrical facade, front verandah and higher rear section.

#### BIBLIOGRAPHY:

- 1. Maryborough RB 1866 No.440.
- 2. Ibid. 1868 No.345.
- 3. Ibid. 1869 No.347; Ibid. 1896 No.446 (Timothy Gaynor owned adjacent vacant land).
- 4. Ibid. 1890 No.420.
- 5. Osborn and Du Bourg, Maryborough, pp.98-99, 232.
- 6. Maryborough RB 1905-6 No.466 (NAV £10).
- 7. Ibid. 1906-7 No.491; Ibid. 1936-37 No.548.
- 8. Osborn and Du Bourg, Maryborough, p.99.
- 9. Maryborough RB 1865 Nos. 455, 457.
- 10. Ibid. 1866 Nos. 439, 441.
- 11. Ibid. 1867 No.467. 12. Ibid. 1892-93 No.426.
- 13. Ibid. 1898-99 No.437 (Thomas Savage, warder, occupier still).

#### CONSERVATION GUIDELINES:

Regular maintenance as necessary.

Collect all roof and ground-water and take well away from the building.

Break up concrete verandah floor and replace with timber to allow ventilation under, which will reduce/eliminate the rising damp problem.

When repainting use original/period paint colours.

If fencing, using original/appropriate period front fence.

### WEATHERBOARD RESIDENCE,

102 INKERMAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries □ Town Plan □ Transport □ Health □ Local Industries □ Socio-economic □ Public and □ Private Building □ Victorian □ Religion □ Notable Men □ Sport and Recreation □ And Women □ Public and Private Planting □ Inter-war Housing □ Post World War Two
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE    Entire Place (Heritage and Site)   Including Other Sites   Other  RECOMMENDATION   Should be conserved - C   Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Designer  Garden Design  Garden Planting  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Historic Significance  Horticultural Significance  Manufacturing Significance  Horticultural Significance  Manufacturing Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual  Unusual Design, Features
DESCRIPTION  Place Contains   Main Building  Outbuilding/s of Significance  Individual Planting of Significance or Interest Significance  Interest as Structures  Part of Garden OR □ Individually Structures  Other  Other  Other □ Other Fences of Significance or Interest  Visible  Visible

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN
DESIGN  ■ Standard ■ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single Single and Part Cellar Single and Full Basement Two Storeys  Two Storeyed Two Storeyed With Part Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials  Original (1) and Later () Section Materials
Walls         □ Brick - Face       □ Brick - Rendered       □ Brick - Painted Later?       □ Corrugated Iron         □ Brick - Probably Painted       □ Stone       Timber Stud Framed/         □ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed         □ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       □ Other         Roof (Main Roof (1), Additions (2)-)       □ Pitched       □ Gabled       □ Lean-to       □ Timber Shingles         □ Flat       □ No Eaves       ■ Narrow Eaves       □ Canvas         □ Wide Eaves       □ Slate Cladding       □ Terracotta Tile       □ Flat Metal Sheet         ■ Corrugated Iron       □ Patent Metal Roofing       □ Timber Shingles       □ Metal Deck         Tiles       Timber Shingles       □ Metal Deck
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required □ Required

Washingtonia filifera (x2), 114 INKERMAN STREET, MARYBOROUGH.

PLANTED:

CIRCA 1920

DEGREE OF SIGNIFICANCE:

OF LOCAL SIGNIFICANCE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION

#### CULTURAL SIGNIFICANCE:

Two fine trees either side of driveway. Poorly suited to character of house and presumably remnant from earlier garden.

#### CONSERVATION GUIDELINES:

No perceived threat. Advise owners of value of trees.

City of Maryborough Heritage Study

TIMBER HOUSE,
106-108 INKERMAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s 1967 □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s ■ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and □ Gold Discoveries □ First Survey and Original □ Local Government and Growth of the Town □ Transport (Mining and Other) □ Socio-economic □ Public and □ Education □ Health Mix in the Town □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Edwardian □ Inter-war Housing □ Post World War Two  DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE
EXTENT OF SIGNIFICANCE Entire Place (Heritage and Site) Including Other Sites  Heritage Item Alone Other  RECOMMENDATION Should be conserved - C POSSIBLE FUTURE SIGNIFICANCE
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect
DESCRIPTION  Place Contains

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE 1960S
DESIGN  ☐ Standard ☐ One-off ☐ Unique ☐ Flat Fronted ☐ Double Fronted ☐ More Than Two Fronts ☐ Other
PLAN  Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
□ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
Tiles  Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  Intact □ Additions □ Alterations □ Secondary Elements □ Part of the Significance □ Part of the Significance □ Detract from the Significance □ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

☐ Part of Garden OR ☐ Individually

☐ Other Fences of Significance or Interest

Front Fence OR

Significance

☐ Visible

☐ Garden or Other

Structures

□ Other

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE 1950S
DESIGN  ☐ Standard ☐ One-off ☐ Unique ☐ Flat Fronted ☐ Double Fronted ☐ More Than Two Fronts ☐ Other
PLAN  Rectangular  Other
STOREYS  □ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS □ All of the One Basic Material ■ Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
☐ Flat ☐ No Eaves ☐ Narrow Eaves ☐ Canvas ☐ Wide Eaves ☐ Slate Cladding ☐ Terracotta Tile ☐ Flat Metal Sheet ☐ Corrugated Iron ☐ Patent Metal Roofing ☐ Timber Shingles ☐ Metal Deck ☐ Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use

## WEATHERBOARD HOUSE,

# 116 INKERMAN STREET, MARYBOROUGH.

	1417 717 1	DOI	.0001.								
	BUILT		1850s 1900s or 1910s 1960s	□ 1º	860s 920s-1930s 970s		1870s 1940s 1980s		1880s or 1 1950s 1990s	890s	
		Explo	ral Settlement [ port ation [	Gold Loca (Min Hea Nota	d Discoveries al Industries ning and Oth	er)	Town F Socio-e Mix in Sport a	Plan conor the T nd Re			Local Government and Growth of the Town Public and Private Building Victorian Edwardian Inter-war Housing
]	EXTE	NT O	F SIGNIFICAN F SIGNIFICAN ENDATION	CE   Should		ce (H tem A d - C	leritage an Alone	d Site		cluding her	Post World War Two Other Sites
	Basis of Arc	f Sign chitec Arch Trad sociati tanica storic nufac	L SIGNIFICANO nificance tural Significance itect esman ions with Person/ al Significance Significance sturing Significance turing Significance arison With Othe al  Unusual	Desig	en Design Body Construction Horticultur Streetscapes in Maryboro	on Si al Si e Sign	gnificance nificance		☐ Garde ☐ Engine ☐ Landsc ☐ Townsc	en Maintering Si ape Sign cape Sig	of Components enance and Development  gnificance inficance nificance  Typical Design, Features
	Place C	Main Outh Sign Gard	ins in Building building/s of iificance den or Other ctures		Garden of S Individual I Interest as □ Part of Front Fence □ Other F	Plant Garde e OF	ting of Sig	nifica ndivid	unce or	Buildi	

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  ■ Rectangular □ Other
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS
All of the One Basic Material  ☐ Two Basic Materials ☐ Original (1) and Later () Section Materials ☐ Walls
Walls         □ Brick - Face       □ Brick - Rendered       □ Brick - Painted Later?       □ Corrugated Iron         □ Brick - Probably Painted       □ Stone       Timber Stud Framed/         □ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed         ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       □ Other         Roof (Main Roof (1), Additions (2)-)       □ Pitched       □ Gabled       □ Lean-to       □ Timber Shingles         □ Flat       ■ No Eaves       □ Narrow Eaves       □ Canvas         □ Wide Eaves       □ Slate Cladding       □ Terracotta Tile       □ Flat Metal Sheet
Corrugated Iron ☐ Patent Metal Roofing ☐ Timber Shingles ☐ Metal Deck Tiles  Windows ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium ☐ Fatent December ☐ Steel Framed ☐ Aluminium
Exterior Doors  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  Intact □ Additions □ Alterations □ Secondary Elements □ Part of the Significance □ Part of the Significance □ Detract from the Significance □ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

# WEATHERBOARD HOUSE,

MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries Town Plan and Growth of the Town □ Transport (Mining and Other)□ Socio-economic □ Public and □ Private Building □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing □ Post World War Two
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  Entire Place (Heritage and Site)  Heritage Item Alone  Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  □ Architect □ Designer □ Builder □ Manufacturer of Components □ Tradesman □ Garden Design □ Garden Planting □ Garden Maintenance and Development □ Associations with Person/Group/Body □ Botanical Significance □ Historic Significance □ Horticultural Significance □ Horticultural Significance □ Manufacturing Significance □ Manufacturing Significance □ In Comparison With Other Places in Maryborough □ Typical □ Unusual □ Unusual Design, Features □ Good Quality Design, Features ■ Typical Design, Features
DESCRIPTION  Place Contains

	☐ Yes No
	USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
	STYLE VICTORIAN?
	DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
	PLAN  ■ Rectangular □ Other
	STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS
)	■ All of the One Basic Material  □ Two Basic Materials  □ Original (1) and Later () Section Materials  Walls
	Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron  Brick - Probably Painted □ Stone
	Corrugated Iron
	Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber □ Metal
)	SIGNIFICANT FEATURES
	INTACTNESS  ■ Intact
	CONDITION  □ Excellent ■ Good ■ Fair □ Substantially Decayed □ Poor □ Remains Only
	FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use  Disused  Abandoned  Unsympathetic Use  Sympathetic Use  Basic Maintenance  Threatened by Adjacent Use  Required  Threatened by Subdivision

### WEATHERBOARD HOUSE.

☐ Other

WEATHER BOARD HOUSE,
120 INKERMAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and □ Gold Discoveries □ First Survey and Original □ Local Government and Growth of the Town □ Transport □ Local Industries □ Town Plan □ Amount of the Town □ Education □ Health □ Mix in the Town □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing □ Post World War Two
DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE  EXTENT OF SIGNIFICANCE ■ Entire Place (Heritage and Site) □ Including Other Sites
RECOMMENDATION Should be conserved - C  Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance
□ Architect □ Designer □ Builder □ Manufacturer of Components □ Tradesman □ Garden Design □ Garden Planting □ Garden Maintenance and Development □ Associations with Person/Group/Body □ Botanical Significance □ Construction Significance □ Engineering Significance □ Historic Significance □ Horticultural Significance □ Landscape Significance □ Manufacturing Significance □ Streetscape Significance □ Townscape Significance □ In Comparison With Other Places in Maryborough □ Typical □ Unusual □ Unusual Design, Features □ Good Quality Design, Features ■ Typical Design, Features
DESCRIPTION  Place Contains   Main Building □ Garden of Significance or Interest □ More than One Main  Outbuilding/s of □ Individual Planting of Significance or Significance □ Interest as □ Building of Significance  Garden or Other □ Part of Garden OR □ Individually Significance  Structures □ Front Fence OR □ Visible

☐ Other Fences of Significance or Interest

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single Single and Part Cellar Single and Full Basement More Than Two Storeys  Two Storeyed Two Storeyed With Part Sasement Cellar  Ellar Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials  Original (1) and Later () Section Materials
Walls       □ Brick - Face       □ Brick - Rendered       □ Brick - Painted Later?       □ Corrugated Iron         □ Brick - Probably Painted       □ Stone       Timber Stud Framed/         □ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed         ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       □ Other         Roof (Main Roof (1), Additions (2)-)       □ Lean-to       □ Timber Shingles         □ Flat       No Eaves       □ Narrow Eaves       □ Canvas         □ Wide Eaves       □ Slate Cladding       □ Terracotta Tile       □ Flat Metal Sheet         ■ Corrugated Iron       □ Patent Metal Roofing       □ Timber Shingles       □ Metal Deck
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  Intact □ Additions □ Alterations □ Secondary Elements □ Part of the Significance □ Part of the Significance □ Detract from the Significance □ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  ☐ In-use ☐ Disused ☐ Abandoned ☐ Threatened by Adjacent Use ☐ Unsympathetic Use ☐ Sympathetic Use ☐ Basic Maintenance ☐ Threatened by Subdivision ☐ Cosmetic Maintenance Required ☐ Threatened by Redevelopment Required



City of Maryborough Heritage Study

# WEATHERBOARD HOUSE,

121 INKERMAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s ■ 1870s ■ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  Exploration and Pastoral Settlement Local Industries Town Plan  Transport (Mining and Other) Socio-economic Public and Private Building  Religion Notable Men Sport and Recreation and Women Public and Private Planting  DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE
EXTENT OF SIGNIFICANCE  Entire Place (Heritage and Site)
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect
DESCRIPTION  Place Contains  Main Building  Outbuilding/s of Significance  Individual Planting of Significance or Building of Significance Significance  Interest as Structures  Part of Garden OR □ Individually Structures  Other  Other  Other  Other  Other Fences of Significance or Interest  U More than One Main Building of Significance Buildings of No Significance Significance U Visible  Visible

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN?
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS
■ All of the One Basic Material  □ More Than Two Basic Materials  □ Original (1) and Later () Section Materials
Walls         □ Brick - Face       □ Brick - Rendered       □ Brick - Painted Later?       □ Corrugated Iron         □ Brick - Probably Painted       □ Stone       Timber Stud Framed/         □ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed         ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       □ Other         Roof (Main Roof (1), Additions (2)-)       □ Other
☐ Pitched ☐ Gabled ☐ Lean-to ☐ Timber Shingles ☐ Flat ☐ No Eaves ☐ Narrow Eaves ☐ Canvas ☐ Wide Eaves ☐ Slate Cladding ☐ Terracotta Tile ☐ Flat Metal Sheet ☐ Corrugated Iron ☐ Patent Metal Roofing ☐ Timber Shingles ☐ Metal Deck ☐ Tiles
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Threatened by Subdivision □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

0
=
=
-
S
7
0
7
S
-
~
O,
0
-



MANILLA BRIGHT DIVIDERS 5 TAB A4



Ref No: 37100 Made in China www.marbig.com



CYANIDE VATS, OFF JOHNSTON, MARYBOROUGH.

CONSTRUCTED:

EARLY 20TH CENTURY?

THEMES ILLUSTRATED BY THIS PLACE:

GOLD MINING

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE:

ALL SURVIVING GOLD MINING REMAINS AND SITE TO A RADIUS OF 30 METRES FROM ANY OF THE CYANIDE VATS

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION

Cyanide Vats Cont.

#### CULTURAL SIGNIFICANCE:

These cyanide vats are apparently the only surviving examples within the Municipality of Maryborough and illustrate an important phase of gold mining. In the Maryborough area the initial alluvial surface mining was soon succeeded by quartz shaft mining. The development of cyanide processing, used to separate the gold from quartz, is particularly associated with the reworking of mullock heaps to obtain gold not previously obtained due to economic or practical reasons. The best and largest cyanide mining site in the Maryborough region is apparently the Golden Point place off Graves Track.

#### HISTORY:

Original Use:

Gold processing site.

Present Use:

Disused

Original and Present Owner:

Crown

#### DESCRIPTION:

Due to later filling and other works, the full extent of the place is not clear - there are apparently two surviving vats. Recent removal of sand/earth have possibly removed a vat.

WEATHERBOARD HOUSE,				
2 KARS STREET, MARYBOROUGH.				
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s				
THEMES IDENTIFIED BY THIS PLACE    Exploration and Pastoral Settlement   Local Industries   Town Plan   Local Government   and Growth of the Town   Public and   Public and   Public and Private Planting   Victorian   Inter-war Housing   Post World War Two				
EXTENT OF SIGNIFICANCE  Entire Place (Heritage and Site)  Heritage Item Alone  RECOMMENDATION  Should be conserved - C  Conservation Area				
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  □ Architect  □ Tradesman  □ Garden Design  □ Garden Planting  □ Garden Maintenance and Development  □ Associations with Person/Group/Body  □ Botanical Significance  □ Historic Significance  □ Horticultural Significance  □ Horticultural Significance  □ Manufacturing Significance  □ Horticultural Significance  □ Townscape Significance  □ In Comparison With Other Places in Maryborough  □ Typical □ Unusual □ Unusual Design, Features □ Good Quality Design, Features  ■ Typical Design, Features				
DESCRIPTION  Place Contains   Main Building □ Garden of Significance or Interest □ More than One Main □ Outbuilding/s of □ Individual Planting of Significance or Significance □ Interest as □ Building of Significance □ Garden or Other □ Part of Garden OR □ Individually Structures □ Front Fence OR □ Visible □ Other □ Other Fences of Significance or Interest				

 $\hfill \Box$  Other Fences of Significance or Interest

HISTORY KNOWN  ☐ Yes No			
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest			
STYLE EDWARDIAN			
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other			
PLAN  Rectangular  Other			
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials  Original (1) and Later () Section Materials  Walls			
Brick - Face			
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal			
SIGNIFICANT FEATURES			
INTACTNESS  Intact  Additions  □ Part of the Significance □ Detract from the Significance □ Detract from the Significance			
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only			
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required			

WEATHERBOARD HOUSE,
3 KARS STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s 1935 □ 1900s or 1910s ■ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and □ Gold Discoveries □ First Survey and Original □ Local Government and Growth of the Town □ Transport □ (Mining and Other) □ Socio-economic □ Public and □ Education □ Health
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  □ Entire Place (Heritage and Site) □ Heritage Item Alone □ Other
RECOMMENDATION Should be conserved - C  ☐ Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Garden Designer  Garden Planting  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Historic Significance  Horticultural Significance  Manufacturing Significance  Streetscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual  Unusual Design, Features  Good Quality Design, Features  Typical Design, Features
DESCRIPTION  Place Contains   Main Building □ Garden of Significance or Interest □ More than One Main □ Outbuilding/s of □ Individual Planting of Significance or Building of Significance □ Significance □ Interest as □ Buildings of No □ Garden or Other □ Part of Garden OR □ Individually Significance □ Structures □ Front Fence OR □ Visible □ Other □ Other □ Other Fences of Significance or Interest

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE 1930S
DESIGN  ■ Standard □ One-off □ Unique □ Flat Fronted ■ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS □ All of the One Basic Materials □ Two Basic Materials ■ More Than Two Basic Materials □ Original (1) and Later () Section Materials
Walls   ■ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed   ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction Other   Roof (Main Roof (1), Additions (2)-) □ Pitched □ Canvas   □ Flat □ No Eaves □ Narrow Eaves □ Canvas   ■ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet   ■ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck   Tiles
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Metal
SIGNIFICANT FEATURES
INTACTNESS  Intact □ Additions □ Alterations □ Secondary Elements □ Part of the Significance □ Detract from the Significance □ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use

# WEATHERBOARD HOUSE,

	WEATHERBOARD HOUSE,
8	MARYBOROUGH.
	BUILT □ 1850s ■ 1860s ■ 1870s ■ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
	THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries Town Plan □ Transport (Mining and Other) Socio-economic □ Public and □ Private Building □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing □ Post World War Two
	DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE  EXTENT OF SIGNIFICANCE ■ Entire Place (Heritage and Site) □ Including Other Sites
	RECOMMENDATION
	CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architectural Significance  Garden Designer  Garden Planting  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Historic Significance  Historic Significance  Manufacturing Significance  Streetscape Significance  Manufacturing Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual  Unusual Design, Features  Good Quality Design, Features  Typical Design, Features
	DESCRIPTION  Place Contains  Main Building  □ Outbuilding/s of Significance □ Garden of Significance or Interest □ More than One Main Building of Significance or Significance □ Individual Planting of Significance or Significance □ Part of Garden OR □ Individually Structures □ Front Fence OR □ Other □ Other □ Other □ Other Fences of Significance or Interest

HISTORY KNOWN  ☐ Yes No				
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest				
STYLE VICTORIAN/EDWARDIAN				
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other				
PLAN Rectangular  Other				
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials				
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls				
□ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone				
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Timber and Glass □ Metal				
SIGNIFICANT FEATURES				
INTACTNESS  ☐ Intact				
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only				
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use				

# WEATHERROARD HOUSE

WEATHERBOARD HOUSE,
11 KARS STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s □ 1897? □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and □ Gold Discoveries □ First Survey and Original □ Local Government and Growth of the Town □ Transport □ (Mining and Other) □ Socio-economic □ Public and □ Public and □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing □ Post World War Two
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  Entire Place (Heritage and Site)  Heritage Item Alone  Conservation Area
D Conservation Fired
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  □ Architect □ Designer □ Builder □ Manufacturer of Components □ Garden Design □ Garden Planting □ Garden Maintenance and Development □ Associations with Person/Group/Body □ Botanical Significance □ Historic Significance □ Horticultural Significance □ Horticultural Significance □ Landscape Significance □ Manufacturing Significance □ Manufacturing Significance □ In Comparison With Other Places in Maryborough □ Typical □ Unusual □ Unusual Design, Features □ Good Quality Design, Features ■ Typical Design, Features
DESCRIPTION  Place Contains  Main Building □ Garden of Significance or Interest □ More than One Main □ Outbuilding/s of □ Individual Planting of Significance or □ Building of Significance □ Buildings of No □ Garden or Other □ Part of Garden OR □ Individually Significance □ Structures □ Front Fence OR □ Visible □ Other □ Other Fences of Significance or Interest

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  ■ Rectangular □ Other
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS
■ All of the One Basic Material  □ More Than Two Basic Materials □ Original (1) and Later () Section Materials  Walls
□ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
Pitched □ Gabled ■ Lean-to □ Timber Shingles □ Flat □ No Eaves ■ Narrow Eaves □ Canvas □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet ■ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

FORMER BRIGIDINE CONVENT, NOW CHRISTIAN COMMUNITY COLLEGE, S.E. CNR. BURKE STREET, 21 KARS STREET, MARYBOROUGH.

BUILT: 1903-1904<sup>1</sup>

THEMES ILLUSTRATED BY THIS PLACE: RELIGION

EDUCATION


DEGREE OF SIGNIFICANCE: LOCAL SIGNIFICANCE


EXTENT OF SIGNIFICANCE: ENTIRE BUILDING, MATURE EXOTIC PLANTING AND SITE

TO A RADIUS OF 40 METRES.

RECOMMENDATIONS: LOCAL PLANNING PROTECTION

CONSERVATION AREA: MARYBOROUGH WEST





Former Brigidine Convent Cont.

#### CULTURAL SIGNIFICANCE:

This former Brigidine Convent has historic significance, is a local landmark, the only surviving convent building in the City and the only Edwardian era non-residential church building. This building is quite well detailed and is very largely intact. Many sizeable Victorian country towns established in the 19th century had Catholic convents set up in them and though often the substantial buildings survive, very few continue in their original use, a reflection of the decline in the Church in the late 20th century and changing religious practices. Kyneton contains one of the most comparable buildings.

#### HISTORY:

Original Use:

Brigidine Convent

Present Use:

Christian Community

College

Original Owner:

Brigidine Sisters

Present Owner:

Christian Community

College

Architect:

William Kell of

Maryborough<sup>2</sup>

Builder:

William Dingle<sup>2</sup>

In 1902 Dr. James Moore, the Bishop of Ballarat, came to Maryborough to make arrangements for the Brigidine Sisters to come. In January six sisters from Ararat arrived and on 3 February opened St. Josephs High School, in addition to taking over St. Augustine's Primary School, which had previously been run by lay teachers. On 22 November the foundation stone was laid, with the school being opened on 26 April.<sup>2</sup> The first Superior (1902-1908) was Mother Mary Josephine Clancy.<sup>2</sup>

#### DESCRIPTION:

Style late Victorian with some Edwardian details. Design fairly standard.

Plan rectangular bisected by a central hallway from the front door in the centre of the symmetrical main facade.

Former Brigidine Convent Cont.

Two storeyed.
Walls solid face brick with cement rendered decoration.
Roof gabled with shallow eaves, slate clad with terracotta

ridging.

Features are the gables, main facade, red face brick walls, front door with its two attached columns and internally the wide stairway, surviving mantelpieces and the leadlight.

#### BIBLIOGRAPHY:

1. Foundation stone laid 22 November 1903 by the Rev. Dr. Moore, Bishop of Ballarat.

2. Betty Osborn and Trenear Du Bourg, Maryborough, City of Maryborough, Maryborough, 1985, p.338.


#### CONSERVATION GUIDELINES:

Regular maintenance as necessary.

Keep interior as original as possible.

When repainting use original/period paint colours in lieu of the present unsympathetic white.

Plant front garden to be appropriate setting for the building.



ST. AUGUSTINE'S ROMAN CATHOLIC CHURCH AND PRESBYTERY, N.E. CNR. BURKE STREET, KARS STREET, MARYBOROUGH.

BUILT:

 $1962^{1}$ 

C.1885? PRESBYTERY<sup>3</sup>

THEMES ILLUSTRATED BY THIS PLACE: RELIGION

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE:

ALL OF BOTH BUILDINGS AND SITES TO A RADIUS OF 30


METRES


**RECOMMENDATIONS:** 


LOCAL PLANNING PROTECTION


CONSERVATION AREA -MARYBOROUGH WEST














St. Augustine's Roman Catholic Church Cont.

bluestone stones in the existing building, are all that remain of this stone church, which survived until the early 1960s when it was demolished to allow the construction of the present building.

#### DESCRIPTION:

Style 1950s and 1960s.

Design one-off.

Plan T-shaped, with projecting tower, entry portico and confessionals also projecting.

Single storeyed with choir gallery at western end.

Walls cavity? bluestone and concrete block.

Roof steeply gabled with shallow boxed eaves, concrete tile clad, with dormers to naves and chancel.

Features are the interior which is intact and complete with original furnishings and fittings; the spire and tower, dormers, mix of bluestone and concrete block walling, the gable screens, foundation stone and the dedication cairn.

#### Presbytery

Style late Victorian.

Design standard.

Plan rectangular.

Single storeyed.

Walls solid face brick.

Roof hipped with shallow eaves, slate clad.


Features are the encircling cast iron verandah, front triple windows, duochromatic chimneys and the symmetrical facade.

#### **BIBLIOGRAPHY:**

- 1. Foundation stone laid 21 January 1962 by The Most Reverend J.P. O'Collins, D.D. Bishop of Ballarat.
- Dedication cairn
   21 June 1979
   by The Most Rev. Ronald A. Mulkearns, Bishop of Ballarat and
   Diamond Jubilee of Priesthood of
   Rev. Fr. Thomas
   A. Scanlan, Priest.
- 3. Betty Osborn and Trenear Du Bourg, Maryborough, City of Maryborough, Maryborough 1985, pp.143-145, 245-246, 273-274.
- 4. F.W. Niven & Co., "View of Maryborough Victoria, Australia", coloured lithograph, published c.1886, City of Maryborough collection.

#### CONSERVATION GUIDELINES:

Keep interior of church intact, as it is now. Regular maintenance as necessary. When repainting use original/period paint colours and placement.



St. Augustine's Roman Catholic Church Cont.

#### CULTURAL SIGNIFICANCE:

St. Augustine's Church has a finely detailed interior which is a very good example of church design from the early 1960s. The bluestone tower and spire, the only stone spire in the City and the only remains of the 1872 Catholic church, remains something of a local landmark though at close quarters it is dominated by the size of the 1962 church building to which it is attached. The exterior design of the latter is unremarkable and constructed out of bluestone blocks from the walls of the first church. All bluestone combined towers and spires are very unusual anywhere in Victoria. The presbytery is one of Maryborough's oldest surviving houses and one of the very small number of brick dwellings.

HISTORY:

Church

Original and Continuing Use:

St. Augustine's Roman

Catholic Church

Original and Continuing Owner:

Roman Catholic Church

Architect:

Builder:

Cost:

Tower and Spire

Architect:

Builder:

Walls Thomas Smith and Mr.

Joseph Broadbent

completed.3

Cost:

 $£1.950^3$ 

Presbytery


Builder:


George Clayfield<sup>3</sup>


St. Augustine's was founded early in 1854 in a timber frame and canvas structure. In 1869 the foundation stone of the first proper church building was laid, with construction being completed in 1872. The present tower and spire, as well as the





1872 CHURCH - F.W. NIVEN & CO., "VIEW OF MARYBOROUGH, VICTORIA", COLOURED LITHOGRAPH, PUBLISHED C.1886, CITY OF MARYBOROUGH COLLECTION











Melia azederach - WHITE CEDAR, KARS STREET, FROM NAPIER STREET TO BURKE STREET, MARYBOROUGH.

PLANTED:

CIRCA 1940

DEGREE OF SIGNIFICANCE:

OF LOCAL SIGNIFICANCE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION



# CULTURAL SIGNIFICANCE:

Effective street tree planting using an Australian native tree to create effective scale and space definition.

# CONSERVATION GUIDELINES:

No perceived threat.

City of Maryborough Heritage Study

# WEATHERBOARD COTTAGE - GRENVILLE,

30 KARS STREET, MARYBOROUGH.				
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s				
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries □ Town Plan □ Transport □ Mix in the Town □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing □ Post World War Two				
DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE  EXTENT OF SIGNIFICANCE Entire Place (Heritage and Site) Including Other Sites  Heritage Item Alone Other  RECOMMENDATION Should be conserved - C  Conservation Area				
CULTURAL SIGNIFICANCE Basis of Significance  Architectural Significance  Garden Designer  Garden Planting  Garden Manufacturer of Components  Garden Manufacturer of Components				
Associations with Person/Group/Body  □ Botanical Significance □ Construction Significance □ Engineering Significance □ Historic Significance □ Horticultural Significance □ Landscape Significance □ Manufacturing Significance ■ Streetscape Significance □ Townscape Significance □ In Comparison With Other Places in Maryborough ■ Typical ■ Unusual □ Unusual Design, Features □ Good Quality Design, Features □ Typical Design, Features				
DESCRIPTION  Place Contains   Main Building  Garden of Significance or Interest  Outbuilding/s of Significance or Interest Building of Significance  Individual Planting of Significance or Building of Significance  Interest as  Garden or Other Part of Garden OR ☐ Individually  Structures  Front Fence OR  Other  Other  Other Fences of Significance or Interest				

HISTORY KNOWN  ☐ Yes No					
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest					
STYLE VICTORIAN/EDWARDIAN					
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other					
PLAN  Rectangular  Other					
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS					
All of the One Basic Material  ☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials					
Walls   □ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed   ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction □ Other   Roof (Main Roof (1), Additions (2)-) □ Lean-to □ Timber Shingles					
□ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet □ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck □ Tiles					
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors					
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber ☐ Metal					
SIGNIFICANT FEATURES					
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance					
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only					
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use Disused Abandoned Threatened by Adjacent Use Unsympathetic Use Sympathetic Use Dasic Maintenance Required Threatened by Redevelopment Required  Threatened by Subdivision					

#### CITY OF MARYBOROUGH HERITAGE STUDY WEATHERBOARD HOUSE, 35 KARS STREET, MARYBOROUGH. BUILT 1850s □ 1860s □ 1870s ■ 1880s or 1890s ■ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1970s ☐ 1980s □ 1990s THEMES IDENTIFIED BY THIS PLACE Exploration and Gold Discoveries First Survey and Original ☐ Local Government Pastoral Settlement Local Industries Town Plan and Growth of the Town Transport (Mining and Other) ☐ Socio-economic ☐ Public and Education ☐ Health Mix in the Town Private Building Religion □ Notable Men □ Sport and Recreation Victorian and Women ☐ Public and Private Planting **Edwardian** ☐ Inter-war Housing ☐ Post World War Two DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE EXTENT OF SIGNIFICANCE Entire Place (Heritage and Site) ☐ Including Other Sites ☐ Heritage Item Alone □ Other RECOMMENDATION Should be conserved - C Conservation Area

#### **CULTURAL SIGNIFICANCE**

Structures

□ Other

Bas	sis of Significanc	e						
20	Architectural Si	gnificance						
	☐ Architect ☐ Tradesman	□Desig		Builder Garden Planting			of Components	
	— Sarden Flanting — Sarden Flanting — Sarden Wantenance and Development					ent		
☐ Botanical Significance ☐ Construction Significance ☐ Engineering Significance								
☐ Historic Significance ☐ Horticultural Significance ☐ Landscape Significance								
☐ Manufacturing Significance ☐ Streetscape Significance ☐ Townscape Significance								
6	In Comparison With Other Places in Maryborough							
	☐ Typical ■	Unusual   Unu	sual Design, Feat	ures Good Qu	uality D	Design, Feature	es 🗆 Typical Design,	, Features
DE	SCRIPTION							
Pla	ce Contains							
	Main Build	ing $\square$	Garden of Sig	nificance or Inter	rest	☐ More	than One Main	
	☐ Outbuilding	/s of	Individual Pla	nting of Significa	ance or		ing of Significance	
	Significance	3	Interest as	5			ings of No	
	☐ Garden or C	ther	☐ Part of Gar	rden OR Individ	dually		ficance	

☐ Other Fences of Significance or Interest

☐ Visible

☐ Front Fence OR

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single Single and Part Cellar Single and Full Basement Two Storeys  Two Storeyed Two Storeyed With Part Storeyed With Part Basement Cellar  Cellar Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials  Two Basic Materials  I Two Basic Materials
□ More Than Two Basic Materials       □ Original (1) and Later () Section Materials         Walls       □ Brick - Face       □ Brick - Rendered       □ Brick - Painted Later?       □ Corrugated Iron         □ Brick - Probably Painted       □ Stone       Timber Stud Framed/         □ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed
Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction  Roof (Main Roof (1), Additions (2)-)  Pitched □ Gabled □ Lean-to □ Timber Shingles □ Flat □ No Eaves □ Narrow Eaves □ Canvas □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet □ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck  Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required


### WEATHERBOARD SHOP BUILDING AND ATTACHED HOUSE,

	,
45 KARS STREET, MARYBOROUGH.	
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890 □ 1900s or 1910s ■ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s	0s 1938?
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and □ Gold Discoveries □ First Survey and Original Pastoral Settlement □ Local Industries □ Town Plan □ Transport □ (Mining and Other) □ Socio-economic □ Health □ Mix in the Town □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting	Inter-war
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  □ Heritage Item Alone  RECOMMENDATION  Should be conserved - C  □ Conservation Area	☐ Post World War Two ding Other Sites
HAIR AFFAI	IR .
☐ Tradesman ☐ Garden Design ☐ Garden Planting ☐ Garden M ☐ Associations with Person/Group/Body ☐ Botanical Significance ☐ Construction Significance ☐ Engineerin ☐ Historic Significance ☐ Horticultural Significance ☐ Landscape	turer of Components Maintenance and Development  ng Significance Significance E Significance Typical Design, Features
DESCRIPTION  Place Contains	fore than One Main uilding of Significance uildings of No gnificance

HISTORY KNOWN  ☐ Yes No
USE  Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE 1930S
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN Rectangular  Other
STOREYS  Single Single Single and Part Cellar Single and Full Basement Two Storeys  Two Storeyed Two Storeyed With Part Basement Cellar  Cellar Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials  More Than Two Basic Materials  Original (1) and Later () Section Materials  Walls
Brick - Face
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  ☐ Exterior Doors ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  Intact
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required □ Required

# WEATHERBOARD HOUSE,

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
Brick - Face
☐ Flat
Windows  ■ Original □ Some Later □ All Later □ Leadlight, Stained Glass ■ Timber □ Steel Framed □ Aluminium  Exterior Doors
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required



ight .

WEATHERBOARD HOUSE,
63 KARS STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s ■ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE    Exploration and
DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE  EXTENT OF SIGNIFICANCE ■ Entire Place (Heritage and Site) □ Including Other Sites
RECOMMENDATION
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  □ Architect  □ Architect  □ Architect  □ Architect  □ Construction Significance  □ Builder  □ Garden Planting  □ Garden Maintenance and Development  □ Associations with Person/Group/Body  □ Botanical Significance  □ Historic Significance  □ Horticultural Significance  □ Horticultural Significance  □ Manufacturing Significance  □ Horticultural Significance  □ Townscape Significance  □ In Comparison With Other Places in Maryborough  □ Typical  □ Unusual  □ Unusual Design, Features  □ Good Quality Design, Features  ■ Typical Design, Features
DESCRIPTION  Place Contains  Main Building □ Garden of Significance or Interest □ More than One Main □ Outbuilding/s of □ Individual Planting of Significance or Significance □ Interest as □ Buildings of No □ Garden or Other □ Part of Garden OR □ Individually Significance □ Visible □ Other □ Other □ Other Fences of Significance or Interest

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials  More Than Two Basic Materials □ Original (1) and Later () Section Materials
Walls         □ Brick - Face       □ Brick - Rendered       □ Brick - Painted Later?       □ Corrugated Iron         □ Brick - Probably Painted       □ Stone       Timber Stud Framed/         □ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed         ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       □ Other         Roof (Main Roof (1), Additions (2)-)       □ Pitched       □ Gabled       □ Lean-to       □ Timber Shingles         □ Flat       ■ No Eaves       □ Narrow Eaves       □ Canvas         □ Wide Eaves       □ Slate Cladding       □ Terracotta Tile       □ Flat Metal Sheet         ■ Corrugated Iron       □ Patent Metal Roofing       □ Timber Shingles       □ Metal Deck
Windows   □ Original □ Some Later □ All Later □ Leadlight, Stained Glass   □ Timber □ Steel Framed □ Aluminium   Exterior Doors   □ Original □ Some Later □ All Later □ Leadlight, Stained Glass   □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required □ Required

☐ Other Fences of Significance or Interest


□ Other

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single Single and Part Cellar Single and Full Basement Two Storeys Two Storeyed Two Storeyed With Part Two Storeyed with Full Basement Cellar  WALLS All of the One Basic Material Two Basic Materials Original (1) and Later () Section Materials
Walls         □ Brick - Face       □ Brick - Rendered       □ Brick - Painted Later?       □ Corrugated Iron         □ Brick - Probably Painted       □ Stone       Timber Stud Framed/         □ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed         ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       □ Other         Roof (Main Roof (1), Additions (2)-)       □ Pitched       □ Gabled       □ Lean-to       □ Timber Shingles         □ Flat       ■ No Eaves       □ Narrow Eaves       □ Canvas         □ Wide Eaves       □ Slate Cladding       □ Terracotta Tile       □ Flat Metal Sheet         ■ Corrugated Iron       □ Patent Metal Roofing       □ Timber Shingles       □ Metal Deck         Tiles
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Threatened by Subdivision □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

## WEATHERBOARD HOUSE - MOVED HERE,

· · · · · · · · · · · · · · · · · · ·
94 KARS STREET, MARYBOROUGH
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s ■ 1980s ■ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and        □ Gold Discoveries       □ First Survey and Original
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  □ Heritage Item Alone  □ Other  RECOMMENDATION  Should be conserved - C  □ Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Garden Designer  Garden Planting  Garden Manufacturer of Components  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Construction Significance  Historic Significance  Horticultural Significance  Manufacturing Significance  Streetscape Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual Design, Features  Typical Design, Features
DESCRIPTION  Place Contains   Main Building  Outbuilding/s of Significance  Individual Planting of Significance or Building of No  Significance  Interest as  □ Buildings of No  Significance  Front Fence OR □ Other

Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  ☐ Other  Single ☐ Single and Part Cellar ☐ Two Storeyed ☐ Two Storeyed With Part ☐ Cellar  Cellar  Cellar  Cellar  Description  Two Storeyed with Full Basement Cellar  WALLS
■ All of the One Basic Material       □ Two Basic Materials         □ More Than Two Basic Materials       □ Original (1) and Later () Section Materials
Walls         □ Brick - Face       □ Brick - Rendered       □ Brick - Painted Later?       □ Corrugated Iron         □ Brick - Probably Painted       □ Stone       Timber Stud Framed/         □ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed         ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       □ Other
Pitched □ Gabled □ Lean-to □ Timber Shingles □ Flat □ No Eaves □ Narrow Eaves □ Canvas □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet □ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck □ Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors ☐ Original ☐ Some Later ☐ Leadlight, Stained Glass
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ■ Intact
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required



## WEATHERBOARD COTTAGE,

96 KARS STREET, MARYBOROUGH
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries Town Plan □ Transport □ Mix in the Town Public and Private Planting □ Victorian □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing □ Post World War Two
DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE  EXTENT OF SIGNIFICANCE  ■ Entire Place (Heritage and Site) □ Including Other Sites
RECOMMENDATION Should be conserved - C  Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  □ Architect  □ Tradesman  □ Garden Design  □ Garden Planting  □ Garden Maintenance and Development  □ Associations with Person/Group/Body  □ Botanical Significance  □ Construction Significance  □ Historic Significance  □ Horticultural Significance  □ Landscape Significance  □ Manufacturing Significance  □ Manufacturing Significance  □ In Comparison With Other Places in Maryborough  □ Typical  □ Unusual  □ Unusual Design, Features  □ Good Quality Design, Features  ■ Typical Design, Features
DESCRIPTION
Place Contains  Main Building □ Garden of Significance or Interest □ More than One Main □ Outbuilding/s of □ Individual Planting of Significance or Significance □ Interest as □ Building of Significance □ Garden or Other □ Part of Garden OR □ Individually Significance □ Visible □ Other □ Other □ Other Fences of Significance or Interest

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single Single and Part Cellar Single and Full Basement More Than Two Storeys  Two Storeyed Two Storeyed With Part Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials  More Than Two Basic Materials  Original (1) and Later () Section Materials
Walls   □ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed   ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction □ Other   Roof (Main Roof (1), Additions (2)-) □ Pitched □ Gabled □ Lean-to □ Timber Shingles   □ Flat ■ No Eaves □ Narrow Eaves □ Canvas   □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet   ■ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Original ☐ Or
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use ☐ Disused ☐ Abandoned ☐ Threatened by Adjacent Use ☐ Unsympathetic Use ☐ Sympathetic Use ☐ Basic Maintenance ☐ Threatened by Subdivision ☐ Cosmetic Maintenance Required ☐ Threatened by Redevelopment Required

Mahonia lumarifolia, 1 KENNEDY STREET, MARYBOROUGH.

PLANTED:


CIRCA 1975

DEGREE OF SIGNIFICANCE:

OF LOCAL SIGNIFICANCE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION



## CULTURAL SIGNIFICANCE:

Especially fine specimen of an unusual shrub, infrequently planted in Maryborough area.

Mahonia lumarifolia Cont.

## CONSERVATION GUIDELINES:

No perceived threat. Inform owner of value of plant.

Araucaria heterophylla - NORFOLK ISLAND PINE, 12 KENNEDY STREET, MARYBOROUGH.

PLANTED:


CIRCA 1960

DEGREE OF SIGNIFICANCE:

OF LOCAL SIGNIFICANCE

RECOMMENDATIONS:

LOCAL PLANNING PROTECTION



## CULTURAL SIGNIFICANCE:

Immature specimen of interesting foliage tree with considerable contribution to streetscape and urban skyline.

Araucaria heterophylla Cont.

## CONSERVATION GUIDELINES:

No perceived threat. Inform owners of the value of the tree.

☐ Other

WEATHERBOARD HOUSE,
19 KENNEDY STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s ■ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and □ Gold Discoveries □ First Survey and Original □ Local Government and Growth of the Town □ Transport □ Local Industries Town Plan and Growth of the Town □ Education □ Health Mix in the Town □ Religion □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Edwardian □ Inter-war Housing □ Post World War Two
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  □ Heritage Item Alone  □ Other  RECOMMENDATION Should be conserved - C
Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect
DESCRIPTION  Place Contains   Main Building □ Garden of Significance or Interest □ More than One Main  Outbuilding/s of □ Individual Planting of Significance or Significance □ Interest as □ Building of Significance  □ Garden or Other □ Part of Garden OR □ Individually Significance  Structures □ Front Fence OR □ Visible

☐ Other Fences of Significance or Interest

HISTORY KNOWN
☐ Yes No
USE
Present Use Same as Original
STYLE LATE VICTORIAN/EDWARDIAN
DESIGN
■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN
Rectangular    Other
STOREYS
Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full  Cellar □ Basement Cellar
WALLS Basement Cellar
All of the One Basic Material  Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
☐ Brick - Face ☐ Brick - Rendered ☐ Brick - Painted Later? ☐ Corrugated Iron
□ Brick - Probably Painted □ Stone Timber Stud Framed/
<ul> <li>□ Vernacular Timber Stud/Split or Sawn Paling Clad</li> <li>■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction</li> <li>□ Other</li> </ul>
Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction  Construction  Other  Roof (Main Roof (1), Additions (2)-)
Pitched
☐ Flat ☐ No Eaves ☐ Narrow Eaves ☐ Canvas ☐ Wide Eaves ☐ Slate Cladding ☐ Terracotta Tile ☐ Flat Metal Sheet
Corrugated Iron
Windows
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium
Exterior Doors
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS
■ Intact □ Additions □ Alterations
☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance
□ Detract from the Significance □ Detract from the Significance
CONDITION
☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed
□ Poor □ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL
☐ In-use ☐ Disused ☐ Abandoned ☐ Threatened by Adjacent Use ☐ Unsympathetic Use ☐ Basic Maintenance ☐ Threatened by Subdivision
☐ Unsympathetic Use ☐ Sympathetic Use ☐ Basic Maintenance ☐ Threatened by Subdivision ☐ Cosmetic Maintenance Required ☐ Threatened by Redevelopment ☐ Required

# WEATHERBOARD HOUSE,

22 KENNEDY STREET,  MARYBOROUGH.  SEE FOLLOWING EVALUATION SHEET FOR THE PALM TREE - L.P.P.  BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s  □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  □ Exploration and Pastoral Settlement □ Local Industries □ Town Plan □ Local Government and Growth of the Town □ Transport □ Health □ Mix in the Town □ Public and □ Private Building □ Notable Men □ Sport and Recreation and Women □ Public and Private Planting □ Inter-war Housing □ Inter-war H
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  Entire Place (Heritage and Site)  Heritage Item Alone  Control  Post World War Two  Including Other Sites  Other  RECOMMENDATION  Should be conserved - C
☐ Conservation Area
CULTURAL SIGNIFICANCE
Basis of Significance  Architectural Significance  □ Architect □ Tradesman □ Garden Design □ Garden Planting □ Garden Maintenance and Development □ Associations with Person/Group/Body □ Botanical Significance □ Historic Significance □ Horticultural Significance □ Horticultural Significance □ Manufacturing Significance □ Manufacturing Significance □ In Comparison With Other Places in Maryborough □ Typical □ Unusual □ Unusual Design, Features □ Good Quality Design, Features ■ Typical Design, Features
DESCRIPTION  Place Contains   Main Building  □ Garden of Significance or Interest □ More than One Main □ Outbuilding/s of □ Significance □ Individual Planting of Significance or □ Significance □ Garden or Other □ Structures □ Front Fence OR □ Other □ Other Fences of Significance or Interest □ Visible

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN?
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  ■ Rectangular □ Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials
☐ More Than Two Basic Materials       ☐ Original (1) and Later () Section Materials         Walls       ☐ Brick - Face       ☐ Brick - Rendered       ☐ Brick - Painted Later?       ☐ Corrugated Iron         ☐ Brick - Probably Painted       ☐ Stone       Timber Stud Framed/         ☐ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed         ☐ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       ☐ Other         Roof (Main Roof (1), Additions (2)-)       ☐ Other
Pitched □ Gabled □ Lean-to □ Timber Shingles □ Flat □ No Eaves □ Narrow Eaves □ Canvas □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet □ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors ☐ Original ☐ Framed ☐ Transport Framed ☐
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Threatened by Subdivision □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required



Trachycarpus futurei - CHINESE FAN PALM, 22 KENNEDY STREET, MARYBOROUGH.

PLANTED:


CIRCA 1920

DEGREE OF SIGNIFICANCE:

OF LOCAL SIGNIFICANCE

RECOMMENDATIONS:

LOCAL PLANNING PROTECTION



## CULTURAL SIGNIFICANCE:

Appears to be remnant tree from pair occupying symmetrical positions in fruit garden. Characteristic strong foliage.

Trachycarpus futurei Cont.

## CONSERVATION GUIDELINES:

Tree appears to be in decline as a result of age.

## WEATHERBOARD HOUSE,

24 KENNEDY STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s ■ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE    Exploration and
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  ☐ Entire Place (Heritage and Site) ☐ Including Other Sites ☐ Heritage Item Alone ☐ Other  RECOMMENDATION Should be conserved - C ☐ Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  □ Architect  □ Architect  □ Architect  □ Tradesman  □ Garden Design  □ Garden Planting  □ Garden Maintenance and Development  □ Associations with Person/Group/Body  □ Botanical Significance  □ Construction Significance  □ Historic Significance  □ Horticultural Significance  □ Landscape Significance  □ Manufacturing Significance  □ Manufacturing Significance  □ Streetscape Significance  □ Townscape Significance  □ Townscape Significance  □ Typical  □ Unusual Design, Features  □ Typical Design, Features
DESCRIPTION  Place Contains

HISTORY KNOWN ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE LATE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN Rectangular  Other
STOREYS  Single Single Single and Part Cellar Single and Full Basement More Than Two Storeys  Two Storeyed Two Storeyed With Part Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials  Original (1) and Later () Section Materials
Walls   □ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed   ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction □ Other   Roof (Main Roof (1), Additions (2)-) □ Lean-to □ Timber Shingles   □ Flat □ No Eaves Narrow Eaves □ Canvas   □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet   ■ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck   Tiles
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Threatened by Subdivision □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

SIMSON MEMORIAL CAIRN, KENNEDY STREET ROAD RESERVE, MARYBOROUGH.

BUILT: 1939<sup>1</sup>

THEMES ILLUSTRATED BY THIS PLACE: EXPLORATION AND PASTORAL

SETTLEMENT


NOTABLE MEN AND WOMEN

DEGREE OF SIGNIFICANCE: LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE: CAIRN, STEPS AND SITES TO

A RADIUS OF 20 METRES

RECOMMENDATIONS: LOCAL PLANNING PROTECTION



## CULTURAL SIGNIFICANCE:

Simson Cairn has historic significance as the sole physical remains of the Maryborough area's first settlers, the Simson brothers, who held the pastoral run here from 1840. The sandstone blocks are the local stone and readily identifiable

Simson Memorial Cairn Cont.

with Maryborough, while the bluestone (basalt) is to be found to the east around Carisbrook and beyond. The elaborate nature of this obelisk and its siting overlooking Maryborough reflects the importance of the Simson brothers to the Maryborough community nearly a century later, in 1939. The pioneer's memorial lookout tower at Bristol Hill on the other side of the City (1932-1933) also illustrates the practice of building lookouts in Victorian country towns during the 1930s, the centenary decade of first European settlement in the State.

Adjacent private planting has largely eliminated the lookout role of the Simson obelisk and it is highly desirable that all such planting is regulated to ensure that both the distant view from the lookout and the residents' privacy are maintained.

### HISTORY:

Original and Continuing Use:

Memorial obelisk.

#### DESCRIPTION:

Stone (faced?) obelisk and base, basalt quoins (and other locations in the base) and local sandstone elsewhere. Concrete steps, galvanised pipe handrails.

#### BIBLIOGRAPHY:

- 1. Information on the obelisk.
- 2. See Volume 2 history, pp.213-.


## CONSERVATION GUIDELINES: .


Keep intact.


Regular maintenance as necessary.

Establish planning controls on the adjacent properties to regulate planting and structures to regain and retain the lookout's original view out over Maryborough.

Negotiate with the adjoining property owners to prune and keep pruned all planting at a height that will regain the full view to the distance, but obviate all overlooking into their properties. Provision of expert advice should allow the selection of replacement planting that will achieve the above aims without the need for regular pruning and this should replace the existing planting (over time).







Artemisia arburescens - WORMWOOD, REAR OF 28 KENNEDY STREET, MARYBOROUGH.

PLANTED:

?

DEGREE OF SIGNIFICANCE:

OF LOCAL SIGNIFICANCE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION



## CULTURAL SIGNIFICANCE:

Unusual hedge, occasionally planted in arid zones of the State. Provides an effective treatment.

## CONSERVATION GUIDELINES:

May be threatened by future development of vacant land. Advise owners of value of hedge.

□ Other

WEATHERBOARD HOUSE,	
12 LOGAN STREET, MARYBOROUGH.	
BUILT □ 1850s □ 1860s □ 1870s □ 1880s or 1890s □ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s	
THEMES IDENTIFIED BY THIS PLACE    Exploration and	
EXTENT OF SIGNIFICANCE  Extent of Significance  Entire Place (Heritage and Site)  Heritage Item Alone  Other  RECOMMENDATION  Should be conserved - C  Conservation Area	
CULTURAL SIGNIFICANCE  Basis of Significance	ture:
DESCRIPTION Place Contains   Main Building □ Garden of Significance or Interest □ More than One Main □ Outbuilding/s of □ Individual Planting of Significance or Significance □ Interest as □ Building of Significance □ Garden or Other □ Part of Garden OR □ Individually Structures □ Front Fence OR □ Visible	

 $\hfill \square$  Other Fences of Significance or Interest

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  ■ Rectangular □ Other
STOREYS  Single Single and Part Cellar Single and Full Basement Two Storeys Two Storeyed Two Storeyed With Part Basement Cellar  Cellar Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials More Than Two Basic Materials Original (1) and Later () Section Materials
Walls         □ Brick - Face       □ Brick - Rendered       □ Brick - Painted Later?       □ Corrugated Iron         □ Brick - Probably Painted       □ Stone       Timber Stud Framed/         □ Vernacular Timber Stud/Split or Sawn Paling Clad       Metal Framed         ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction       □ Other         Roof (Main Roof (1), Additions (2)-)       □ Pitched       □ Gabled       ■ Lean-to       □ Timber Shingles         □ Flat       □ No Eaves       ■ Narrow Eaves       □ Canvas         □ Wide Eaves       □ Slate Cladding       □ Terracotta Tile       □ Flat Metal Sheet         ■ Corrugated Iron       □ Patent Metal Roofing       □ Timber Shingles       □ Metal Deck
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required

## WEATHERBOARD HOUSE AND SIDE FERNERY,


23 LOGAN STREET, MARYBOROUGH.
BUILT □ 1850s □ 1860s □ 1870s ■ 1880s or 1890s ■ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s
THEMES IDENTIFIED BY THIS PLACE  Exploration and Pastoral Settlement   Gold Discoveries   First Survey and Original Pastoral Settlement   Local Industries   Town Plan   and Growth of the Town   Public and   Public and   Public and   Private Building   Victorian   Edwardian   Inter-war Housing   Post World War Two
DEGREE OF SIGNIFICANCE  EXTENT OF SIGNIFICANCE  □ Heritage Item Alone  □ Other  RECOMMENDATION  Should be conserved - C  □ Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  Architect  Garden Designer  Garden Planting  Garden Maintenance and Development  Associations with Person/Group/Body  Botanical Significance  Historic Significance  Horticultural Significance  Manufacturing Significance  Streetscape Significance  Townscape Significance  In Comparison With Other Places in Maryborough  Typical  Unusual  Unusual Design, Features  Good Quality Design, Features  Typical Design, Features
DESCRIPTION  Place Contains  ■ Main Building □ Garden of Significance or Interest □ More than One Main  ■ Outbuilding/s of □ Individual Planting of Significance or Significance □ Interest as □ Buildings of No  □ Garden or Other □ Part of Garden OR □ Individually Significance □ Structures □ Front Fence OR □ Visible  □ Other □ Other Fences of Significance or Interest

☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN Rectangular  Other
STOREYS  Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys  Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS  All of the One Basic Material □ Two Basic Materials  More Than Two Basic Materials □ Original (1) and Later () Section Materials
Walls   □ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed/   ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction □ Other   Roof (Main Roof (1), Additions (2)-) □ Pitched □ Gabled □ Lean-to □ Timber Shingles   □ Flat No Eaves □ Narrow Eaves □ Canvas   □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet   ■ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck   Tiles
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors □ Original □ Some Later □ All Later □ Leadlight, Stained Glass □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required □ Required

## WEATHERBOARD HOUSE,

# 34 LOGAN STREET,

MARYBOR	OUGH.										
BUILT □	1850s 1900s or 1910s 1960s		1860s 1920s-1930s 1970s		1870s 1940s 1980s		1880s o 1950s 1990s	or 1890	S		1895?
THEMES II	DENTIFIED BY	THI	SPLACE								
•	port tion [	Lo (M L) Ho L) No	old Discoveries ocal Industries Mining and Othealth otable Men and Othealth otable Men and Women		Town Socio- Mix in Sport a	Plan econor the T and Re		1		and	cal Government I Growth of the Town lic and Private Building Victorian Edwardian Inter-war Housing Post World War Two
DEGREE O	F SIGNIFICAN	CE	LOCAL SIGNI	IFICA	ANCE						
RECOMME	F SIGNIFICAN  ENDATION		■ Entire Plac  ☐ Heritage It  Ild be conserved	em A	lone	nd Site	e)	Include Other		Othe	er Sites
			Conservation A	rea							



### **CULTURAL SIGNIFICANCE**

Basis of	Significance	
----------	--------------	--

□ Other

Dasis	of Significance							
A	Architectural Significance	9						
	☐ Architect	□ Design	ner		Builder		Manu	facturer of Components
	Tradesman	□Garde	n Design		Garden Planting			en Maintenance and Development
	Associations with Person/	Group/B	ody					F-11-11-1
	Botanical Significance		Construct	ion S	Significance	□ E	ngine	ering Significance
	Historic Significance						-	ape Signficance
	Manufacturing Significan	ce	Streetscap	e Si	gnificance			cape Significance
I I	n Comparison With Othe	r Places	in Marybo	roug	h			1 8
	☐ Typical ☐ Unusual	☐ Unus	sual Design,	Feat	ures Good Qu	uality I	esign,	Features Typical Design, Features
DESC	CRIPTION							
Place	Contains							
1	Main Building		Garden of	Sign	nificance or Inter	rest		More than One Main
	Outbuilding/s of		Individua	l Pla	nting of Significa	ance of	r	Building of Significance
	Significance		Interest as	3				Buildings of No
	Garden or Other		☐ Part o	f Gar	den OR Individ	dually		Significance
	Structures		Front Fen			,		□ Visible

☐ Other Fences of Significance or Interest

HISTORY KNOWN  ☐ Yes  No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN Rectangular  Other
STOREYS  Single Single and Part Cellar Single and Full Basement More Than Two Storeys  Two Storeyed Two Storeyed With Part Basement Cellar  Cellar Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials  Original (1) and Later () Section Materials
Walls   □ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed   ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction □ Other   Roof (Main Roof (1), Additions (2)-) □ Gabled ■ Lean-to □ Timber Shingles   □ Flat □ No Eaves ■ Narrow Eaves □ Canvas   □ Wide Eaves □ Slate Cladding □ Terracotta Tile □ Flat Metal Sheet   ■ Corrugated Iron □ Patent Metal Roofing □ Timber Shingles □ Metal Deck
Windows   ■ Original □ Some Later □ All Later □ Leadlight, Stained Glass   ■ Timber □ Steel Framed □ Aluminium   Exterior Doors   □ Original □ Some Later □ All Later □ Leadlight, Stained Glass   □ Timber □ Timber and Glass □ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required □ Required



WEATHERBOARD HOUSE, 7 LOWENSTEIN STREET, MARYBOROUGH.

BUILT: 1900S

THEMES ILLUSTRATED BY THIS PLACE: PRIVATE BUILDING -

EDWARDIAN

SOCIO-ECONOMIC MIX


DEGREE OF SIGNIFICANCE: LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE: ENTIRE BUILDING AND SITE

RECOMMENDATIONS: LOCAL PLANNING PROTECTION

CONSERVATION AREA - MARYBOROUGH EAST







- 2 -

Weatherboard House Cont.

## CULTURAL SIGNIFICANCE:

This residence is one of just three substantial dwellings in East Maryborough built prior to 1920, is one of just a few such buildings east of the railway line and illustrates both the sort of dwelling built for the well-off person and the social mix in residential areas during the 19th and early 20th centuries. The uniformly modest 19th century and 1900s dwellings in the adjacent streets illustrate the norm and the contrast in size of both building and site, as well as detailing provide a clear illustration of the economic base of those residents at that time. The City of Maryborough is characterised by the lack of wealth illustrated in its dwellings and this is a reflection of the capital that established the gold mines from the 1860s until 1917 coming from outside Maryborough, such as Ballarat and Melbourne, and to where all of the profits went, rather than staying in the town.

HISTORY:

Original and Continuing Use:

Residence

#### DESCRIPTION:

Style late Victorian.

Design standard.

Plan rectangular.

Single storeyed.


Walls timber stud construction, weatherboard clad.


Roof hipped with shallow eaves, corrugated iron clad.

Features are the encircling cast iron decorated verandah, recessed front door, front triple windows, entrance steps and the mature eucalypt in the front garden.

## CONSERVATION GUIDELINES:

Regular maintenance as necessary.





Weatherboard House Cont.

### Rear Outbuilding

Rectangular in plan. Walls weatherboard. Roof corrugated iron.


#### CONSERVATION GUIDELINES:

External repainting, in original/period/appropriate colours. Repair verandah.
Maintenance as necessary.
Replace frieze with original (original design) or appropriate one.

## WEATHERBOARD COTTAGE,

10 LOWENSTEIN STREET, MARYBOROUGH.
BUILT ☐ 1850s ☐ 1860s ☐ 1870s ☐ 1880s or 1890s ☐ 1900s or 1910s ☐ 1920s-1930s ☐ 1940s ☐ 1950s ☐ 1960s ☐ 1970s ☐ 1980s ☐ 1990s
THEMES IDENTIFIED BY THIS PLACE    Exploration and
EXTENT OF SIGNIFICANCE Entire Place (Heritage and Site) Including Other Sites  Heritage Item Alone Other  RECOMMENDATION Should be conserved - C  Conservation Area
CULTURAL SIGNIFICANCE  Basis of Significance  Architectural Significance  □ Architect □ Designer □ Builder □ Manufacturer of Components □ Tradesman □ Garden Design □ Garden Planting □ Garden Maintenance and Development □ Associations with Person/Group/Body □ Botanical Significance □ Construction Significance □ Engineering Significance □ Historic Significance □ Horticultural Significance □ Landscape Significance □ Manufacturing Significance □ Streetscape Significance □ Townscape Significance □ In Comparison With Other Places in Maryborough □ Typical □ Unusual □ Unusual Design, Features □ Good Quality Design, Features ■ Typical Design, Features
DESCRIPTION  Place Contains  Main Building  Outbuilding/s of Significance  Individual Planting of Significance or Building of Significance  Interest as Individually Significance  Part of Garden OR ☐ Individually Structures  Other  Other  Other  Other  Other  Other  Other  Other  Other

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN?
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN Rectangular  Other
STOREYS  Single Single Single and Part Cellar Single and Full Basement Two Storeys Two Storeyed Two Storeyed With Part Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials
Walls   □ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron   □ Brick - Probably Painted □ Stone Timber Stud Framed/   □ Vernacular Timber Stud/Split or Sawn Paling Clad Metal Framed   ■ Weatherboard Clad Timber Stud Framed/Metal Stud Framed Construction □ Other   Roof (Main Roof (1), Additions (2)-) □ Pitched ■ Gabled ■ Lean-to □ Timber Shingles   □ Flat ■ No Eaves □ Narrow Eaves □ Canvas
☐ Wide Eaves ☐ Slate Cladding ☐ Terracotta Tile ☐ Flat Metal Sheet ☐ Corrugated Iron ☐ Patent Metal Roofing ☐ Timber Shingles ☐ Metal Deck ☐ Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber ☐ Metal
SIGNIFICANT FEATURES  REPLACEMENT_OF THE ORIGINAL TWELVE PANE FRONT WINDOWS IN 1992/1993 HAS REDUCED THE SIGNIFICANCE OF THIS BUILDING
☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use □ Disused □ Abandoned □ Threatened by Adjacent Use □ Unsympathetic Use □ Sympathetic Use □ Basic Maintenance □ Cosmetic Maintenance Required □ Threatened by Redevelopment Required



WEATHERBOARD HOUSE,
REAR MUD BRICK BUILDING,
WEATHERBOARD OUTBUILDING,
2 CANARY ISLAND PALM TREES AND
2 MONTERY CYPRESS TREES,
7 LUKE COURT,
MARYBOROUGH.

SEE FOLLOWING EVALUATION FOR THE TREES.

BUILT:

1900S?

THEMES ILLUSTRATED BY THIS PLACE:

PRIVATE BUILDING -

EDWARDIAN

DEGREE OF SIGNIFICANCE:

LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE:

ALL OF THE 3 BUILDINGS, MATURE EXOTIC PLANTING AND SITES TO A RADIUS OF

50 METRES

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION



- 2 -

Weatherboard House Cont.

#### CULTURAL SIGNIFICANCE:

Now closely subdivided, this former farmhouse is one of the very few such buildings anywhere in the City of Maryborough, which is almost all urban or native forest. The house itself is a largish one and typical in design and detailing for the 1880s, 1890s and 1900s in Victoria. The large paired front windows and its size are the only early 20th century details in the building. The entire building is surprisingly intact apart from the removal of the verandah post capitals and frieze, which was almost certainly all metal. The rear mud brick building most probably survives from the previous occupancy of the site, a mud brick building/s being recorded in the Rate Books. The Canary Island palm trees typify planting around country and urban houses during the early 20th century and are not common in Maryborough. The 1950s? successor to this building is close by to the north.

HISTORY:

Original Use:

Farm house?

Present Use:

Suburban dwelling.

DESCRIPTION:

#### House

Standard late 19th century and 1900s house. Rectangular floor plan, symmetrical front elevation with hallway bisecting the interior, basically three rooms deep.
Single storeyed.
Weatherboard walls.
Hipped corrugated iron roof with central valley gutter.
Timber windows and doors.
Encircling all timber verandah.

#### Mud Brick Building

Rectangular plan - original function unknown. Single storeyed. Walls mud brick. Roof corrugated iron.

Phoenix canariensis (x2) - CANARY ISLAND PALM
 AND Cupressus macrocarpa (x3) - MONTEREY CYPRESS,
7 LUKE COURT,
MARYBOROUGH.

PLANTED:

CIRCA 1910

DEGREE OF SIGNIFICANCE:

OF LOCAL SIGNIFICANCE

**RECOMMENDATIONS:** 

LOCAL PLANNING PROTECTION



## CULTURAL SIGNIFICANCE:

Group of trees, remnant of early gardens around nineteenth century house. Cypressus provided windbreaks while palms offered strongly foliaged decorative element.


#### CONSERVATION GUIDELINES:

Threat appears to lie in modernisation of house and improvement of setting. Inform owner of value of trees.

A.

.

#### WEATHERBOARD HOUSE, 6 MCKEAN STREET, MARYBOROUGH. BUILT □ 1850s □ 1860s □ 1870s 1880s or 1890s ■ 1900s or 1910s □ 1920s-1930s □ 1940s □ 1950s □ 1960s □ 1970s □ 1980s □ 1990s THEMES IDENTIFIED BY THIS PLACE Exploration and ☐ Gold Discoveries ☐ First Survey and Original ☐ Local Government Pastoral Settlement Local Industries Town Plan and Growth of the Town Transport ☐ Public and (Mining and Other) ☐ Socio-economic Education ☐ Health Mix in the Town Private Building Religion □ Notable Men ☐ Sport and Recreation Victorian and Women ☐ Public and Private Planting Edwardian ☐ Inter-war Housing ☐ Post World War Two DEGREE OF SIGNIFICANCE LOCAL SIGNIFICANCE EXTENT OF SIGNIFICANCE Entire Place (Heritage and Site) Including Other Sites ☐ Heritage Item Alone □ Other RECOMMENDATION Should be conserved - C



Conservation Area

#### **CULTURAL SIGNIFICANCE**

Structures

□ Other

~ ~		02	
Ba	sis of Significance		
	Architectural Significance	ce	
	☐ Architect	Designer	☐ Builder ☐ Manufacturer of Components
	☐ Tradesman	☐Garden Design	
	Associations with Person	/Group/Body	
	Botanical Significance	☐ Constr	ruction Significance
	Historic Significance	☐ Hortic	cultural Significance   Landscape Signficance
	Manufacturing Significan	nce Streets	scape Significance   Townscape Significance
	In Comparison With Oth	er Places in Mary	yborough
	☐ Typical ☐ Unusual	☐ Unusual Desi	sign, Features 🔲 Good Quality Design, Features 🔳 Typical Design, Features
DE	SCRIPTION		
Pla	ce Contains		
	Main Building	☐ Garder	en of Significance or Interest
	☐ Outbuilding/s of	☐ Individ	dual Planting of Significance or Building of Significance
	Significance	Interes	st as 🔲 Buildings of No
	☐ Garden or Other	☐ Pa	art of Garden OR ☐ Individually Significance

☐ Other Fences of Significance or Interest

☐ Visible

☐ Front Fence OR

HISTORY KNOWN  ☐ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE VICTORIAN/EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  ■ Single □ Single and Part Cellar □ Single and Full Basement □ More Than Two Storeys □ Two Storeyed □ Two Storeyed With Part □ Two Storeyed with Full Basement Cellar  WALLS
■ All of the One Basic Material  □ More Than Two Basic Materials  □ Original (1) and Later () Section Materials  Walls
□ Brick - Face □ Brick - Rendered □ Brick - Painted Later? □ Corrugated Iron □ Brick - Probably Painted □ Stone
Gabled Lean-to Timber Shingles  Flat No Eaves Narrow Eaves Canvas  Wide Eaves Slate Cladding Terracotta Tile Flat Metal Sheet  Corrugated Iron Patent Metal Roofing Timber Shingles  Tiles
Windows  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Steel Framed □ Aluminium  Exterior Doors  Original □ Some Later □ All Later □ Leadlight, Stained Glass  Timber □ Timber and Glass □ Metal
The state of the s
SIGNIFICANT FEATURES  INTACTNESS  Intact □ Additions □ Alterations □ Secondary Elements □ Part of the Significance □ Part of the Significance □ Detract from the Significance □ Detract from the Significance
CONDITION  □ Excellent □ Good □ Fair □ Substantially Decayed □ Poor □ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use  Disused  Abandoned  Threatened by Adjacent Use  Unsympathetic Use  Sympathetic Use  Basic Maintenance  Cosmetic Maintenance Required  Threatened by Redevelopment  Required

WEATHERBOARD HOUSE AND IN-GROUND TANK, 8 MCKEAN STREET, MARYBOROUGH.

SEE FOLLOWING EVALUATION SHEET FOR THE PEPPERCORN TREES.

BUILT: CIRCA 1890/1900


THEMES ILLUSTRATED BY THIS PLACE: PRIVATE BUILDING - VICTORIAN/EDWARDIAN

DEGREE OF SIGNIFICANCE: LOCAL SIGNIFICANCE

EXTENT OF SIGNIFICANCE: ENTIRE BUILDING AND SITE

RECOMMENDATIONS: LOCAL PLANNING PROTECTION

CONSERVATION AREA: MARYBOROUGH EAST



- 2 -

Weatherboard House Cont.

#### CULTURAL SIGNIFICANCE:

This building is a good intact example of a timber house from the late 19th century/1900s and survives intact on one of the biggest allotments anywhere in urban Maryborough. This larger than usual block gives this building a unique setting in the City.

#### HISTORY:

Original and Continuing Use:

Dwelling

#### DESCRIPTION:

Style late Victorian.

Design standard.

Plan basically rectangular.

Single storeyed.

Walls timber stud construction, weatherboard clad.

Roof gabled with shallow eaves, corrugated iron clad.

Features are the slightly convex roofed cast iron verandah, symmetrical flat front, triple windows, quite steep main roof, red face brick chimneys and the domed in-ground tank.

#### CONSERVATION GUIDELINES:

Catch up on neglected maintenance.

Repaint in original/period/appropriate paint colours and placement.


Ensure all roof and ground-water is collected and carried well away from the building, using ogee profile spouting and round downpipes for replacement elements.

Connect downpipes into in-ground tank.

Regular maintenance as necessary.

Install replica of original front fence or other appropriate one.

Preferably undertake some planting around building.



in.

Schinus areira (x2) - PEPPERCORN, 8-10 MCKEAN STREET, MARYBOROUGH.


PLANTED:

CIRCA 1910

DEGREE OF SIGNIFICANCE:

OF LOCAL SIGNIFICANCE

RECOMMENDATIONS: LOCAL PLANNING PROTECTION



#### CULTURAL SIGNIFICANCE:

Two fine trees in an otherwise vacant landscape apart from timber cottage. Remnants of earlier garden planting which provide a fine scale to the cottage.

#### CONSERVATION GUIDELINES:

No perceived threat unless the block is developed at some future time. Advise owners of value of trees.

Individual Planting of Significance or

☐ Part of Garden OR ☐ Individually

☐ Other Fences of Significance or Interest

Interest as

Front Fence OR

Building of Significance

Buildings of No

Significance

☐ Visible

□ Outbuilding/s of

Significance

☐ Garden or Other

Structures

□ Other

□ Yes No
USE  ■ Present Use Same as Original □ Different Original Use □ Known Later Use or Interest
STYLE EDWARDIAN
DESIGN  ■ Standard □ One-off □ Unique ■ Flat Fronted □ Double Fronted □ More Than Two Fronts □ Other
PLAN  Rectangular  Other
STOREYS  Single Single Single and Part Cellar Single and Full Basement Two Storeys  Two Storeyed Two Storeyed With Part Sasement Cellar  Cellar Basement Cellar  WALLS  All of the One Basic Material Two Basic Materials
☐ More Than Two Basic Materials ☐ Original (1) and Later () Section Materials Walls
Brick - Face
☐ Flat ☐ No Eaves ☐ Narrow Eaves ☐ Canvas ☐ Wide Eaves ☐ Slate Cladding ☐ Terracotta Tile ☐ Flat Metal Sheet ☐ Corrugated Iron ☐ Patent Metal Roofing ☐ Timber Shingles ☐ Metal Deck ☐ Tiles
Windows  ☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Steel Framed ☐ Aluminium  Exterior Doors
☐ Original ☐ Some Later ☐ All Later ☐ Leadlight, Stained Glass ☐ Timber ☐ Timber and Glass ☐ Metal
SIGNIFICANT FEATURES
INTACTNESS  ☐ Intact ☐ Additions ☐ Alterations ☐ Secondary Elements ☐ Part of the Significance ☐ Part of the Significance ☐ Detract from the Significance ☐ Detract from the Significance
CONDITION  ☐ Excellent ☐ Good ☐ Fair ☐ Substantially Decayed ☐ Poor ☐ Remains Only
FACTORS WHICH COULD INFLUENCE THE PLACE'S SURVIVAL  In-use

